

# e-Authorization

8/23/20  
04:48:52

3-Authorization number PA03512338 Reference no: 71459 Status: Approved Approved by maist Approved date 8/23/2023  
 Billing Name Address VIN Retail sold on

34 Basden's American RV  
 600 E Baseline Rd  
 Evansville, IN 47725

4YDTSGL26R7100117

Lu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5100216B	Battery Cable Enc	0.00	0.50	0.50		1	0.20	Complaint: BATTERY CABLES ARE PULLED OUT OF TERMINALS Cause: Battery cables pulled out of terminals. Correction: Installed new battery cable ends. Rerouted wires to prevent cables from pulling out of cable ends again. Secured all wires in place with cable ties. Relocated brakeaway switch for a direct pull.
2	5101206A	Coax, TV - Repair	0.00	1.20	1.00		1	0.30	Complaint: THE TEST TV WILL NOT PICK UP CHANNELS Cause: Test TV will not pick up channels. Correction: Removed booster from wall. Checked all coax connectors on back of booster. Found one connector to be shorted. Cut off connector and install a new one. Checked TV operation again. Still not picking up channels. Removed ceiling mount cable connection in bedroom. Found another coax to be shorted. Cut off connector and installed a new one. Checked operation of test TV again. This time it picks up channels. All three Antenna locations pick up channels. Remounted booster and ceiling plate.

KRV - Approved as a Goodwill gesture (non-warranty).

KRV - Labor time adjusted allowing for proper repair procedure to be performed.

3-Authorization number PA03512338 1.50

paper claims only use one pre-authorization number per warranty claim for

multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the