



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71459
Promised Date:
18 AUG 23



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 71459

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: IN PREAUTH
Author: BH
Location: 0825 CHECK PREAUTH

Stock #: 11170
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 260BHC
Chassis #: 4YDTSGL26R7100117
Serial #: 4YDTSGL26R7100117
Mileage: 0
Licence:

Invoice #:
Date In: 15 AUG 23
Promised: 18 AUG 23
Date Sched:
Completed: 23 AUG 23
Warr. Date:

Job #BUNKHOUSE - Internal

COMPLAINT: PRE DELIVERY INSPECTION NEW BUNKHOUSE

CAUSE: BUNKHOUSE - PRE DELIVERY INSPECTION NEW BUNKHOUSE.

CORRECTION: Moved unit into shop from sales lot. Checked roof and awning. Checked lug nuts and set tire pressure at 75 psi. Checked entrance door and all compartment doors. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked power cord. Checked all electrical outlets and GFCI outlets. Checked converter output. Applied all company decals. Added water to fresh water tank. Flushed all antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Filled all holding tanks and checked monitor panel. Performed LP drop test and set LP pressure at 10 1/2 in.wc. Checked operation of AC, refrigerator, microwave, and range. Used test TV to check TV Antenna. Test TV will not pick up channels. Drained all holding tanks. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	8.00	N/C	N/C
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #1 - Warranty

COMPLAINT: BATTERY CABLES ARE PULLED OUT OF TERMINALS

CAUSE: Battery cables pulled out of terminals.

CORRECTION: Installed new battery cable ends. Rerouted wires to prevent cables from pulling out of cable ends again. Secured all wires in place with cable ties. Relocated brakeaway switch for a direct pull.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	80.00



Subtotal for Job #1: 80.00

Job #2 - Warranty

COMPLAINT: THE TEST TV WILL NOT PICK UP CHANNELS

CAUSE: Test TV will not pick up channels.

CORRECTION: Removed booster from wall. Checked all coax connectors on back of booster. Found one connector to be shorted. Cut off connector and install a new one. Checked TV operation again. Still not picking up channels. Removed ceiling mount cable connection in bedroom. Found another coax to be shorted. Cut off connector and installed a new one. Checked operation of test TV again. This time it picks up channels. All three Antenna locations pick up channels. Remounted booster and ceiling plate.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	160.00

Subtotal for Job #2: 160.00

Parts Total: 0.00
 Labour Total: 240.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 240.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Aug 2023

W/O: 71459
Promised Date: 18 AUG 23



Customer #: 1000
BASDEN'S AMERICAN RV,

