

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13091C

Date In:	02 MAR 26	Author:	KOTT
Promised Date:	04 JUL 26	Stock No:	11478
:	:	Year:	2026
Customer Name:	17940 - REEKIE, TODD	Manufacturer:	FOREST RIVER
Address:	925 LEMONWEIR PARKWAY	Brand:	PUMA DESTINATION
:	TOMAH, WI	Model:	403LFT
Postal/Zip:	54660	Miles/Hrs:	0
Phone#(res):	608-487-2391	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	CHIKO546600@YAHOO.COM	Tag#:	DB: 3/10
Purchased Date:	14 APR 26	:	:
Delivery Date:	14 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS20TP106971	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 -The upper windows      W    1021    FORES
        have sticky silicone all over them
        inside and out
        CAUSE:      Windows have a lot of smeared clear
        silicone smeared on them
        CORRECTION: I used quick solve and a rag to scrub
        the silicone off I had to scrub
        vigourously to get it off  REQ: .75
        AUTH: .75
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Roof needs a bit of  W    1021    FORES
        sealant around antenna plumbing vent
        CAUSE:      Sealant gaps
        CORRECTION: Cleaned areas then used some left over
        dicor from a different job to seal the
        areas REQ: .50  AUTH: DENIED
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Carpet on steps is    W    1021    FORES
        installed uneven and sharp staples
        sticking up through carpeting
        CAUSE:      Mfg installed carpet uneven and
        protruding staples
        CORRECTION: I used a flat scraper and brought up
        carpet fibers to hide the bare edge then
        removed staples that were sticking up
        then used staple gun to get the top
        steps carpet to lay flat were it meets
        the front of next step going up  REQ:
        .40  AUTH: .40
WARR    COMPLAINT:  WARRANTY REPAIR 5 - 5 White ceiling trim W    1021    FORES
```

Continued on page 2

Work Order : 13091C

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
strips are cut too short and no white
silicone to even hide the fact plenty of
white silicone smeared all over trim
though
CAUSE:      Mfg cut trim to short
CORRECTION: I used white silicone to fill end gaps
REQ: .50   AUTH: .50
WARR COMPLAINT: WARRANTY REPAIR 10 - The paper covered   W   1021   FORES
valance left of the table is missing
color from it like it's been scraped
CAUSE:      Scraped
CORRECTION: Used wood crayon to try to blend colors
REQ: .30   AUTH: .10
WARR COMPLAINT: WARRANTY REPAIR 11 - Trim between paper   W   1021   FORES
covered valances above kitchen sink has
a huge gap very unsightly
CAUSE:      Large gap
CORRECTION: Filled with putty REQ: .20 AUTH: .10
WARR COMPLAINT: WARRANTY REPAIR 12 - Center drawer below W   1021   FORES
wardrobe the glides are bent really bad
this exact drawer on 2 other units same
place same thing
CAUSE:      Someone put slide in and drawer was open
and it tweaked the glides of drawer Bent
broken drawer glide ORDER NEW DRAWER
GLIDE      1 3/8" WIDE x 13 3/4" Please
order extras and the back bracket that
holds them in place Non self closing
type
CORRECTION: Tried repairing at first then ordered
new I had to look for one rear bracket
new order had none and one was damaged I
found one and then installed 2 new
cabinet glides tested drawer opens and
closes as it should .....
replaced drawer glides- now checks okay
WARR COMPLAINT: WARRANTY REPAIR 16. front lift the   W   1021   FORES
corner edge of cabinet has a big gouge
out of it
CAUSE:      Gouged corner of cabinet
CORRECTION: I first used putty to fill area I then
found wood marker to blend and match
REQ: .20   AUTH: .20

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
WARR1 822051455 DRAWER SLIDE, 14" CABINET M W-1021      2      2.12      4.24
WARR1 82201344  DRAWER SLIDE, 14" DRAWER GU W-1021      2      0.62      1.24

```

Continued on page 3

Work Order : 13091C

```

*****
Job#  Lab Code  Description    LABOUR    Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.36    140.00    50.40
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.03    140.00     4.20
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.11    140.00    15.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.48    140.00    67.20
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.02    140.00     2.80
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.48    140.00    67.20
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.02    140.00     2.80
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    140.00    70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00    140.00     0.00
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    140.00    70.00
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00    140.00     0.00
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.49    140.00    68.60
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00    140.00     0.00
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.01    140.00     1.40
ARR12 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    140.00    70.00
ARR12 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00    140.00     0.00
ARR16 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    140.00    70.00
ARR16 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.00    140.00     0.00
ARR12 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50    140.00    70.00

```

```

*****
Job #  Excode    Description    EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1021    1.00      0.00      0.00
ARR12  FRT        FREIGHT      W-1021    0.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021        5.48      630.00      0.00      0.00      0.00      635.48

Totals          5.48      630.00      0.00      0.00      0.00      635.48

```

&k2S
&k0S