

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71505
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50350 - DAVID FISCHER
Address: 5512 RYAN LN

47712

Phone: 8127745016

Stock Number: 2022 CATALINA 5ZT2CAZB8NX026806

VIN: 5ZT2CAZB8NX026806 HIN:

SER#: 5ZT2CAZB8NX026806

Mileage: Work Order Comp: 26 DEC 23

Auth. No: Dealer #:

Warr. Date: Work Order Date: 21 AUG 23 Inv #: 399616

WO # Job # Description JOB INFORMATION

71505 2 OUTDOOR KITCHEN DOOR CATCHES WHEN TRYING TO CLOSE
Door is hitting on all corners. Strut on rear of door is coming loose from door. Door is also pushed towards the rear of the frame. Suggest getting new door and decals. Door Remove old door. Put foam tape on new door. Remove old silicone on siding. Install new door. Remove door and taped shims for proper gap around door. Put door back. Taped off and siliconed.

71505 6 LEAK IN LARGE SLIDE ROOM AT EACH CORNER AT THE FLOOR. HAS DAMAGED THE WOOD ALONG THE FLOOR AN EACH SIDE
Ran slide room out. Took a ladder and inspected seals. The Wiper seal on the rear of the slide room was cut too short. The front side wiper seal has been glued to the inside seal and isn't sealing properly. Need to remove silicone and wiper seals and replace with new on both sides. ***there is also a piece of metal above slide room that needs sealed.*** Seals
Removed both side seals and bulb seals. Installed new seals and put bulb seals back. Siliconed . And super glued tops together.

71505 7 WATER LEAK AND DAMAGE IN OUTSIDE KITCHEN.
Pulled unit into bay. Hooked up to water. Pressurized system. Ran water through sink. Check plumbing. Went inside and ran water through bathroom sink, toilet, and shower. After running water in shower I noticed water leaking into the bottom of the bathroom cabinet and also running through the wall and into the outdoor kitchen. Wood

Claim : 71505

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
                Sealed shower surround and where the shower pan and wall meet.
                Let dry. Tested for leaks. No leaks present. Remove drawers.
                Remove cover. Remove damaged wood stile on bottom. Cut new stile
                and drill pilot holes. Staple back 3/4" surport. Install new
                piece. Put drawers back and silicone bottom edge.

71505      4      THERE IS A HOLE IN BEDROM SLIDE ROOM RUBBER MEMBRANE ON BACK
                FRONT SIDE OF THE FACIA
                Small hole on the rubber membrane that wraps around slide room
                facia.
                Applied a piece of extreme tape over hole.

71505      5      HANGER ROD SUPPORT IN FRONT CLOSET HAS COME LOOSE
                Middle support came loose. Support is held mainly with staples
                and one screws.
                Applied liquid nails where the wood stiles meet. Installed screw
                to pull together. Let dry. Installed support to ceiling.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100297855    2    DOOR, BAGGAGE BK MT SILVER PS WHI    1.00      696.84      696.84
F100278555    2    GRAPHIC, DC #7 RH MC 2022 203267    1.00       13.36       13.36
APP017-412406  2    CLEAR SIKASIL PLUS                    1.00       16.59       16.59
346810        6    Seal - Co-Extruded - Wiper - Sing    16.00        2.93       46.88
F100285154    6    STILE, 18MM" X 1-1/2" X 8' CHILI     16.00        0.52        8.32
F100285187    6    2.5" STILE                            8.00        0.87        6.96
6631          7    STILE, LC 18MM" X 5-1/4" X 8' SQU     8.00        1.52       12.16
F100285188    7    3" CABINET STILE                      16.00        0.91       14.56
F100130672    7    7/8" BATTEN VIPER TRUFFLE             10.00        1.71       17.10
F100130671    7    BATTEN, #195 GABLE LATTE, 7/8" X     10.00        1.96       19.60

```

```

*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      2    MISC LABOUR CODE (EXTERNAL)            0.40      160.00       64.00
Z990      2    MISC LABOUR CODE (EXTERNAL)            0.60      160.00       96.00
Z990      2    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            2.00      160.00      320.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)            0.00      160.00        0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)            5.00      160.00      800.00

```

Claim : 71505

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.30     160.00     48.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00     160.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.20     160.00     32.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT        2    FREIGHT - JOBS 2,6,7      1.00     207.02     207.02
FRT        6    UPS-SEAL                  1.00      19.53      19.53
FRT        7    FREIGHT - BATTEN          1.00      32.41      32.41

```

```

Parts Total:      852.37
Labour Total:    1,360.00
Sublet Total:      0.00
Extras Total:     258.96

```

>>>> Claim Total: 2,471.33

Customer Signature: _____

Date: _____