



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71523
Promised Date:
24 AUG 23

CUSTOMER WORK ORDER

WO #: 71523

Customer: 53961 - HAMBLIN, STEPHEN
- 432-296-3318

Tag:

Author: PH

Location: 0906 CHECK PREAUTH

Stock #: 10462

Stock Desc: 2023 TT RIVERSIDE RV
RETRO 135

Chassis #: 59CRD151XPL006785

Serial #: 59CRD151XPL006785

Mileage:

Licence:

Invoice #:

Date In: 22 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 31 AUG 23

Warr. Date: 29 AUG 23

Job #BUNKFINAL - Internal

FINAL PDI NEW BUNKHOUSE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	2.00	N/C	N/C
E210	E210 2-pk BLK ROUND BAGGAGE DOOR CATCH	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #1 - Internal

ADD SECOND BATTERY AND BOX

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #2 - Warranty

COMPLAINT: FRIDGE DOES NOT WORK

CAUSE: Removed doors, hinges, mounting brackets. Pulled fridge. Installed latches and doors. Plugged into bench tester. Fridge came on. Going to let run overnight. Fridge is functional. Removed doors and brackets. Cut out damaged wires. Installed wire connectors. Installed Fridge to cutout. Installed brackets, hinges, doors. Cleaned up area. Parked unit in wash bay.



Customer #: 53961
HAMBLIN, STEPHEN



CORRECTION: .Removed doors, hinges, mounting brackets. Pulled fridge. Installed latches and doors. Plugged into bench tester. Fridge came on. Going to let run overnight. Fridge is functional. Removed doors and brackets. Cut out damaged wires. Installed wire connectors. Installed Fridge to cutout. Installed brackets,hinges, doors. Cleaned up area. Parked unit in wash bay.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	160.00
Subtotal for Job #2:			240.00

Job #3 - Warranty

COMPLAINT: THERE IS A 110 VOLT OUTLET NEAR THE BED THAT IS CRACKED.

CAUSE: Electrical receptical next to bed is cracked and broken due to tightening mounting screws too tight.

CORRECTION: Removed damaged receptical from wall. Removed back of receptical and pulled out wires. Installed wires in new receptical and secured. Mounted new receptical in wall. Checked operation of new receptical. OK.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts				
Part #	Description	Qty	Price	Total
72-7197	15 AMP DECOR RECEPTACLE WITH COVER -	1.00	8.66	8.66
Subtotal for Job #3:				56.66

Parts Total:	8.66
Labour Total:	288.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	296.66

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Sep 2023

