



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71531
Promised Date:
24 AUG 22

CUSTOMER WORK ORDER

WO #: 71531 (Appointment Date: 23 AUG 2023 - Time: 07:00am)

Customer: 28425 - AMES, EDWARD M. - Stock #: 11160

816-309-5609

Tag: 8-29GAVE TO MATT TO ORDER

Author: BJW

Location: 0910 CHECK WORK

Stock Desc: 2022 TT COACHMEN

SPIRIT 1943RB

Chassis #: 5ZT2SBHB2NS043804

Serial #: 5ZT2SBHB2NS043804

Mileage: 0

Licence:

Invoice #:

Date In: 23 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 31 AUG 23

Warr. Date: 29 APR 22

Job #1 - Warranty

COMPLAINT: THERE IS A WATER LEAK COMING FROM THE REFRIGERATOR AREA. CUSTOMER HAS ADVISED THAT THERE ARE MANY TIMES THAT THERE MIGHT BE 1/2" OF ICE ON THE BACK WALL OF THE REFRIGERATOR. SEE HISTORY FROM CUSTOMER'S LAST VISIT. WHEN CUSTOMER CHECKED IN UNIT, BJW WENT OUT AND LOOKED AT REFRIGERATOR WITH CUSTOMER. FOUND THAT THE FREEZER AND REFRIGERATOR DOORS ARE NOT CLOSING VERY GOOD. WHEN REFRIGERATOR ACTS UP, THE WATER FROM INSIDE THE REFRIGERATOR RUNS OUT THE DOOR AND INTO THE FLOOR. THE LEAKING WATER IS ALSO CAUSING THE WOOD BELOW THE REFRIGERATOR TO SWELL.

CAUSE: I put a light into the refer. And closed door. Could see light through the top I installed space in lower hinge. And also removed spacer under the catch and filed the back to pull in tighter. The refer ran water out the bottom. And soaked the wood. And made it swell. And wood needs replaced. water damage

CORRECTION: Remove converter. Remove water heater access panel. Remove lower refrigerator cover. Remove damaged wood. Cut and reinstall new wood. Staple three quarter inch trim back to new wood. Put refrigerator cover back. Put panel back. Put converter back.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00

Parts

Part #	Description	Qty	Price	Total
7556	STILE, 3/4" X 5" X 8' SQ VW LC MONTI	1.00	16.47	16.47

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-STILE	1.00	30.35	30.35

Subtotal for Job #1: 206.82



Customer #: 28425
AMES, EDWARD M.

W/O: 71531
Promised Date: 31 AUG 23

Parts Total:	16.47
Labour Total:	160.00
Sublet Total:	0.00
Extras Total:	30.35
WORK ORDER TOTAL:	206.82

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 Sep 2023



Customer #: 28425
AMES, EDWARD M.

