

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71554
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 51233 - NICHOLAS DEUTSCH
Address: 3700 E BASELINE RD
EVANSVILLE, IN
47725

Phone: 812-664-8746

Stock Number: 2021 SPRINGDALE SG282BH

VIN:

HIN:

SER#: 4YDT28220M3109175

Mileage:

Work Order Comp: 30 AUG 23

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 28 AUG 23

Inv #: 395739

WO # Job # Description JOB INFORMATION

71554 1 METAL SIDING ON OFF DOOR SIDE TOWARDS FRONT IS COMING LOOSE.
CUSTOMER CALLED KEYSTONE AND THEY TOLD HIM IT WOULD BE COVERED
UNDER THE 3 YEAR WARRANTY.
Pulled unit into shop. Removed insert trim. Removed screws for
radius trim. Took heat gun and heated butol tape. Pulled trim
away from front cap and wall. Went inside and removed blind and
window mounting bracket. Went out side and heated butol tape with
heat gun. Pulled wires down. Cleaned butol tape off window and
cut out. Ran slide room out. Cut silicone around slide room
hardware. Removed mounting screwsfor slide room. Took a pry bar
and pulled room out so I could get metal to pull out if channel.
Pulled out top piece that was loose and secured with staples.
Placedmetal back into track. Pulled next panel and secured with
staples. Placed metal in track. Installed foam on back of window.
Secured window and blind to unit. Cleaned area around window.
Applied tape around window. Applied silicone around window and
cleaned excess off. Removed tape. Secured radius trim to front
cap and wall. Installed insert trim . Cleaned excess butol tape
off. Taped trim. Applied silicone. Cleaned excess silicone.
Removed tape. Cleaned up mess. Parked unit.
Pulled unit into shop. Removed insert trim. Removed screws for
radius trim. Took heat gun and heated butol tape. Pulled trim
away from front cap and wall. Went inside and removed blind and
window mounting bracket. Went out side and heated butol tape with
heat gun. Pulled wires down. Cleaned butol tape off window and
cut out. Ran slide room out. Cut silicone around slide room

Claim : 71554

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
hardware. Removed mounting screwsfor slide room. Took a pry bar
and pulled room out so I could get metal to pull out if channel.
Pulled out top piece that was loose and secured with staples.
Placedmetal back into track. Pulled next panel and secured with
staples. Placed metal in track. Installed foam on back of window.
Secured window and blind to unit. Cleaned area around window.
Applied tape around window. Applied silicone around window and
cleaned excess off. Removed tape. Secured radius trim to front
cap and wall. Installed insert trim . Cleaned excess butol tape
off. Taped trim. Applied silicone. Cleaned excess silicone.
Removed tape. Cleaned up mess. Parked unit.

```

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      1    MISCELLANEOUS REPAIR      0.48     160.00     76.80
Z990      1    MISCELLANEOUS REPAIR      0.45     160.00     72.00
Z990      1    MISCELLANEOUS REPAIR      0.65     160.00    104.00
Z990      1    MISCELLANEOUS REPAIR      3.42     160.00    547.20

Parts Total:           0.00
Labour Total:          800.00
Sublet Total:           0.00
Extras Total:           0.00

>>>>> Claim Total:      800.00

```

Customer Signature: _____

Date: _____