

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71592
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 54082 - AMANDA PARKE
Address: 692 S DEER HAVEN DR PRINCETON, IN

47670

Phone: 812-215-0678

Stock Number: 11273 - 2024 CATALINA SUMMIT SERIES 164BHX 5ZT2CAECXRK006719
VIN: 5ZT2CAECXRK006719 HIN: SER#: 5ZT2CAECXRK006719
Mileage: 0 Work Order Comp: 29 APR 24
Auth. No: Dealer #:
Warr. Date: 06 OCT 23 Work Order Date: 31 AUG 23 Inv #: 403628

WO # Job # Description JOB INFORMATION

71592 3 STEP MOUNTS ARE BENT
Step mounts are bending
Took pictures. Step mount are bending up into the underbelly. Put
in po for new step mounts to or a better setup.

71592 5 BATON STRIP IS LOOSE BY THE BATHROOM DOOR
Baton strip falling off lower wall.
Took pictures. Got the staple gun then stapled the baton strip
back on lower wall.

71592 6 FRONT CAP METAL IS DENTED
Front cap metal has dents Metal
Took pictures. Got with Ben about front cap. Showed Denny front
cap,he asked if I took pictures. Un pack crates. Remove right
side front trim. Clean off silicone and putty. Cut off raised
areas on the inside where the screws go. Took pics. Same with
left trim. Remove diamond plate. Remove running lights. Remove
both front panels. Staple on trim on front wood to space out from
screws. Took pics. Cut flat alpha dicor with a knife to make sure
trim lays flat. Install upper metal. Install lower metal. Install
diamond plate. Put corners on. Put new top trim on. Put back
vinyl insert. Put three tubes of alpha on. Taped off and
siliconed. Put on new decals. Test running lights.

71592 7 120V OUTLET IS MISSING COVER TRIM
Bunk bed area is missing the outlet cover.

Claim : 71592

 WO # Job # Description JOB INFORMATION

Matt gave me a new 120v outlet. Removed the outlet then put in new outlet with cover. Tested the outlet.

71592 1 SEALER ON WATER HEATER TRIM IS LEAKING
 Trim was not seal properly
 Took pictures . When draining the water heater, water leaks into interior floor. Removed the factory silicone the put clear silicone down the rub silicone into cracks.

71592 2 TOILET IS LEAKING
 Leaking hose to toilet
 Went inside camper to dewinterize and noticed antifreeze coming from toilet. Unscrew the hose from toilet to verify it had a Cone washer. It had a one washer. The hose was loose when removing. Put hose back on and tightened. No more leaks after tightening the waterline. Took pictures

71592 4 WATER PUMP NEEDS GROUNDED LIGHTS FLICKERING
 When the water pump runs, the led lights flicker.
 When the water pump runs, the led lights flicker. Went to the underbelly and cut the ground. Wired the ground to the frame. Checked lights when waterpump runs now lights don't flicker after.

 Part No Job# Description PARTS Qty Price Total

733555	3	1/8x2x36 ANGLE		1.00	20.29	20.29
392575	5	FLAT TRANSITION TRIM BLACK OR WHI		1.00	12.06	12.06
C01299075	6	LABEL, USA MASS LABEL INFO (LARG		1.00	3.76	3.76
F100418583	6	GRAPHIC, #20 FRONT "CATALINA" CAT		1.00	15.09	15.09
F100418582	6	GRAPHIC, #17 FRONT MOUNTAINS CATA		1.00	11.03	11.03
F100418581	6	GRAPHIC, #16 ODS CATALINA SUMMIT		1.00	1.31	1.31
F100418580	6	GRAPHIC		1.00	1.31	1.31
F100162292	6	METAL, .040 48 X 96 CTL SL BLACK		2.00	102.96	205.92
392575	6	FLAT TRANSITION TRIM BLACK OR WHI		1.00	12.06	12.06
3388	6	551LSB-1 BLACK NON SAG DICOR		1.00	7.69	7.69
8695	6	5121 ALPHATHANE - WHITE		3.00	10.52	31.56
500627	6	CLEAR SIKASIL PLUS		2.00	17.86	35.72
F100336521	6	DECAL, 41" COACHMEN W/ PETE LEGEN		1.00	10.71	10.71
72-7197	7	15 AMP DECOR RECEPTACLE WITH COVE		1.00	8.66	8.66

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00

Claim : 71592

```

*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.30    160.00     48.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.10    160.00     16.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      3.00    160.00    480.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    160.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      3.00    160.00    480.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.00    170.00      0.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.30    160.00     48.00
Z990      1    MISC LABOUR CODE (EXTERNAL)      0.20    160.00     32.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.20    160.00     32.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.30    160.00     48.00

```

```

*****
Excode    Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT      6    FREIGHT FOR DECALS ON JOB#6      1.00     23.10     23.10
FRT      6    FREIGHT & CRATE - METAL      1.00    763.30    763.30
FRT      6    FREIGHT & CRATE - METAL      1.00    385.57    385.57
FRT      6    UPS-DECAL      1.00     17.30     17.30

```

```

Parts Total:      377.17
Labour Total:    1,184.00
Sublet Total:        0.00
Extras Total:    1,189.27

```

>>>> Claim Total: 2,750.44

Customer Signature: _____

Date: _____