



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71594



CUSTOMER WORK ORDER

WO #: 71594

Customer: 53911 - WAHNSIEDLER,
JAMES T. - 812-598-9696

Tag:

Author: BH

Location: 0915 CHECK PREAUTH

Stock #: 11173

Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC9RK006713

Serial #: 5ZT2CAEC9RK006713

Mileage: 0

Licence:

Invoice #:

Date In: 31 AUG 23

Promised:

Date Sched:

Completed: 14 SEP 23

Warr. Date: 30 AUG 23

Job #BUNKHOUSE - Internal

Transferred to BAS*71648 on 09 SEP 23

Estimate amount was 0.00

PRE DELIVERY INSPECTION NEW BUNKHOUSE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #BUNKFINAL - Internal

Transferred to BAS*71648 on 09 SEP 23

Estimate amount was 0.00

FINAL PDI NEW BUNKHOUSE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #E2 - Internal

Transferred to BAS*71648 on 09 SEP 23

Estimate amount was 0.00

10K E2 EQUALIZER HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #E2: 0.00

Job #BCWT - Internal

Transferred to BAS*71648 on 09 SEP 23

Estimate amount was 0.00

BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

Labor



Customer #: 53911
WAHNSIEDLER, JAMES T.



Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BCWT: 0.00

Job #1 - Warranty

COMPLAINT: WATER PUMP NEEDS GROUNDING CAUSES LIGHTS TO FLICKER

CAUSE: Water pump doesn't have a good ground

CORRECTION: Cut then negative side of water pump wires the spliced in wire to ground to frame. Took pictures

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	48.00

Subtotal for Job #1: 48.00

Job #2 - Internal

COMPLAINT: ENTRY STEP MOUNTS ARE BENDING

CAUSE: Steps fall downward

CORRECTION: Took pictures. Put in po for new step mount or better step mounts.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: RIGHT SIDE FENDER LINER IS NOT COMPLETE

CAUSE: Fender

CORRECTION: Remove long leg fender. Cut back siding . Put fender back. Tape off and siliconed. Also put extream tape over exsposed wood.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	32.00

Subtotal for Job #3: 32.00

Parts Total:	0.00
Labour Total:	80.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	80.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 53911
WAHNSIEDLER, JAMES T.

