



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71611
Promised Date:
08 SEP 23

CUSTOMER WORK ORDER

WO #: 71611

Customer: 54002 - MARCHAND,
MICHAEL - 812-499-4391
Tag: BEN SENT IN PREAUTH
Author: BH
Location: 0921 BH TO CLOSE

Stock #: 10893
Stock Desc: 2023 TT KEYSTONE
SPRINGDALE 285TL
Chassis #: 4YDTSGN22P3100455
Serial #: 4YDTSGN22P3100455
Mileage: 0
Licence:

Invoice #:
Date In: 05 SEP 23
Promised: 08 SEP 23
Date Sched:
Completed: 21 SEP 23
Warr. Date: 19 SEP 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT PDI NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Checked all running lights. One clearance light on rear not lighting up. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Recorded all tire serial numbers. Checked roof and sealed a few spots. Checked powercord. Checked awning canvass. Rear arm on awning will not open up. Shock on arm isn't working. Checked all interior lights. Checked converter output. Added water to fresh water tank. Flushed antifreeze from water lines and faucets. Opened bypass on water heater. Connected to city water and filled. Purged all air from water system. Added Quick disconnect to LP line to check LP pressure. Performed LP drop test and set LP pressure at 10 in.wc. Checked all appliances. Checked TV Antenna, TV, Radio and Fireplace. Retracted power stab jacks. Dumped all holding tanks. Water heater is full and ready to camp. Moved unit to washbay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1200 - Internal

COMPLAINT: INSTALL EQUALIZER 1200 WEIGHT DISTRIBUTION HITCH

CAUSE: EQUALIZ INSTALL EQUALIZER 1200 WEIGHT DISTRIBUTION HITCH

CORRECTION: Assembled hitch ball to hitch head. Mounted hitch brackets on frame of unit. Relocated brake away switch to allow mounting of hitch bracket.

SETUP HITCH HIGHT AND HOOKED UP TO TRAILER. ADJUSTED AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C



Customer #: 54002
MARCHAND, MICHAEL





Parts

Part #	Description	Qty	Price	Total
14-2928	12,000LB. EQUALIZER ADJ HITCH	1.00	N/C	N/C
14-8623	2-5/16"X1-1/4" X 2-5/8" 12K BALL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1200: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: RED CLEARANCE LIGHT NOT BRIGHT

CAUSE: REAR CLEARANCE LIGHT NOT WORKING

CORRECTION: Removed rear clearance light. Connected new light to wiring. Mounted new light. Checked operation of new light. OK. Resealed around light with clear silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	32.00

Parts

Part #	Description	Qty	Price	Total
210628	MCL0032RBS 1-LED RED MARKER LIGHT	1.00	4.31	4.31

Subtotal for Job #1: 36.31

Job #2 - Internal

COMPLAINT: REAR AWNING ARM STRUT DOESN'T HAVE ANY PRESSURE AND DOESN'T HOLD THE ARM UP

CAUSE: NO PICS NO INFO NO NOTES

Parts

Part #	Description	Qty	Price	Total
358231	Awning - Hardware - For Hardware - 1	2.00	N/C	N/C
382268	Awning - Strut - Gas - 124 Lb - For	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-STRUT & WASHERS	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Parts Total: 4.31
 Labour Total: 32.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 36.31

