



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71630
Promised Date:
26 SEP 23



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 71630

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag: BH SENT IN PREAUTH

Author: BH

Location: 0929 BH TO CLOSE

Stock #: 10845

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE GREY WOLF 23MKBL

Chassis #: 4X4TCKY29PK085838

Serial #: 4X4TCKY29PK085838

Mileage: 0

Licence:

Invoice #:

Date In: 07 SEP 23

Promised: 30 SEP 23

Date Sched:

Completed: 30 SEP 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: VALANCE AND BLIND FELL DOWN BEHIND
DINETTE WHILE SITTING ON LOT

CAUSE: WINDOW VALANCE AND ROLLER SHADE FELL DOWN WHILE IN SHOWROOM

CORRECTION: Window valance wood is split at mounting points. Roller shade is bent and will not stay in mounting clips. Parts need replaced. Turned in parts request for a new window valance and a new roller shade. 9/27/23: Received new parts. Transferred shade mounting clips from damaged part to new part. Added extra Brad nails to hold valance together. Mounted roller shade and curtains to new valance. Mounted new valance and new roller shade over dinette window. Secured in place with screws. Moved unit back to show room.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts

Part #	Description	Qty	Price	Total
F100141513	SHADE, 64" X 24" ZEBRA SHADE / 2020	1.00	75.05	75.05
F100061628	VALANCE, WINDOW	1.00	57.50	57.50

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SHADE	1.00	30.40	30.40
FRT	UPS-VALANCE	1.00	30.44	30.44

Subtotal for Job #1: 225.39

Parts Total: 132.55
Labour Total: 32.00
Sublet Total: 0.00
Extras Total: 60.84
WORK ORDER TOTAL: 225.39

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

