

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71659
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 54010 - PAMELA KEBORTZ
Address: 5800 MARTIN RD
NEWBURGH, IN
47630
Phone: (812) 453-0867
Stock Number: 2022 XLR 321
VIN:
Mileage:
Auth. No:
Warr. Date:

HIN:
Work Order Comp: 21 OCT 23
Dealer #:
Work Order Date: 12 SEP 23
SER#: 4X4FXLH24NF169496
Inv #: 397679

WO # Job # Description JOB INFORMATION

71659 4 THE LIVING ROOM THERMOSTAT COVER FELL OFF AND IT DOES NOT WORK
NOW
Can't get just the cover for the thermostat. Needs new
thermostat.
Removed thermostat. Installed new thermostat.

71659 7 THE REFRIGERATOR DOOR COMES OPEN WHILE IN TOW.
Slide room floor is not secured to the walls. Floor is pushing
down. This has caused the fridge to push upper brackets out of
the stile above the fridge. Fridge is bouncing up and down as the
unit is in travel. **slide room ski is also damaged under the
fridge. Will need to remove slide ski and secure the floor so it
doesn't move and replace slide ski. Also need to shim the fridge
so it will not pull down on stile. **are we replacing the stile?
Fridge falling out. And floor loose.
Remove trim on floor of slide room. Put panel on floor to roll
fridge out. Unscrew fridge and roll out. Cut a 25 and a 1/2 inch
angle, iron and drilled holes in it. Screw to wall and floor.
Took pics. Put fridge back in fastened. Nailed trim back on
floor. Remove left floor ski. And installed new floor ski.

71659 5 BATHROOM DOOR WILL NOT OPEN ONCE IT IS SHUT. WHEN TURNING THE
DOOR KNOB, IT DOES NOT PULL THE STRIKER IN FAR ENOUGH TO LET IT
UNLATCH.
AJD DOOR
Removed stricker plate. Took a chisel and cut a relief into the

Claim : 71659

 WO # Job # Description JOB INFORMATION

door frame so it will sit flush. Installed plate. Cleaned up
 debris. Door now opens with handle.

 Part No Job# Description PARTS Qty Price Total

 DOM3316250.71 4 BLK SINGLE ZONE LCD THERMOSTAT 1.00 60.46 60.46
 F100380780 7 J&B SLIDE SKI, 53", CURRENT 2022, 1.00 9.98 9.98

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.15 160.00 24.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 1.89 160.00 302.40
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.41 160.00 65.60
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.59 160.00 94.40
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.51 160.00 81.60
 Z990 7 MISC LABOUR CODE (EXTERNAL) 1.60 160.00 256.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 7 UPS-SKI 1.00 30.44 30.44

Parts Total: 70.44
 Labour Total: 840.00
 Sublet Total: 0.00
 Extras Total: 30.44

>>>> Claim Total: 940.88

Customer Signature: _____

Date: _____