

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1683498
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAMB7RU042400
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT231MKS-8
		DEALER RO #	71717
		CLAIM START DATE	09/21/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	10-9-01-00-000158	Operational Description	
		Stabilizer Jack - Bolt On, each - Frame & Chassis/Levelers, Underbelly/Replace/No Tread Code	
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-09-21 11:24:14 :: RR STAB JACK ROD IS BENT Bent rod on scissor jack NEED TO REPLACE THE JACK			
Model #		Dlr Sub Hrs	0.40
Serial #		Appr Hrs	0.30
		Sub Labor Amt	\$64.00
		Appr Labor Amt	\$48.00
Notes			
EXCESSIVE AMOUNT REQUESTED CHANGED TO SIMILAR REPAIR TIME			

Labor

Line# 2

Operation Code	70-151-01-00-001800	Operational Description	
		Refrigerator Door - Appliances/Refrigerator (House Type)/Replace/No Tread Code	
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-09-21 11:28:24 :: FRIDGE DOOR ON THE BOTTOM HAS 2 DENTS IN TI Dent in bottom door NEED TO REPLACE THE DOOR Additional Note : bhoffman@americanrvcenter.com, 2023-09-21 11:31:06 :: THE GREEN TAPE THAT IS ON THE DOOR WAS YOURS !!!			
Model #	GPV10FSNBSB	Dlr Sub Hrs	1.00
Serial #	HT589595	Appr Hrs	0.20
		Sub Labor Amt	\$160.00
		Appr Labor Amt	\$32.00
Notes			
EXCESSIVE AMOUNT REQUESTED CHANGED TO FLAT RATE INSTALL DAMAGE			

Labor

Line# 3

Operation Code	30-101-24-00-001079	Operational Description	
		Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code	
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-09-21 11:31:26 :: BEDROOM DOOR OFF TRACK Bedroom door Bedroom door off track,put door back on track and adjusted,			
Model #		Dlr Sub Hrs	0.30
Serial #		Appr Hrs	0.30
		Sub Labor Amt	\$48.00
		Appr Labor Amt	\$48.00
Notes			

Labor
Line# 4

Operation Code
40-196-01-11-001306

Operational Description
LED Light - Electrical/12 Volt Interior/Replace/Electrical

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-09-21 11:34:02 :: BATHROOM LIGHT MISSING COVER Light cover ISNTALL NEW LIGHT COVER

Model #	Dir Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

Submitted	Labor Amt	\$304.00	Approved	Labor Amt	\$160.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$304.00		Total	\$160.00

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.