

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1687269
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4SHR703PN117591
USA		CHASSIS VIN	
		MILEAGE	0

Labor rate: \$160.00

OWNER INFORMATION

DANIEL VANBIBBER

6855 N State Rd 161
Gentryville, IN 47537
USA

SITE/WAREHOUSE	400 / 400C
ITEM #	HRHS-8801
DEALER RO #	71762
CLAIM START DATE	09/25/2023
CLAIM END DATE	01/01/1900

Retail Date of Purchase 03/04/2023

WARRANTY EXPIRATION DATE 03/04/2024

Claim Line Details

Labor

Line# 1	Operation Code 40-124-01-11-002631	Operational Description Exterior Solar Panel Port or Inlet - Electrical/Solar Power/Replace/ Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-09-25 15:50:49 :: SOLAR PANEL CONNECTIONS THE RED ONE IS BROKEN Solar plug roof mount Took pictures of solar plug roof mount. The positive side of the solar roof mount is broken. There is no damage to or on the roof. Put in po for new roof solar plug.	
	Model #	Dlr Sub Hrs 0.30 Sub Labor Amt \$48.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$32.00

Notes

Labor

Line# 2	Operation Code 20-65-01-00-000656	Operational Description Skylight - Exterior Dome - Exterior/Skylights/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-09-25 16:04:03 :: THE SKYLIGHT OVER THE BATHROOM IS PEALING UP CHECK AND ADVISE Roof Sealer not sticking to skylight Took pictures of sealer not sticking to skylight. Sealer needs pilled and new sealer applied, but need to scuff the the surface before applying new sealer.	
	Model #	Dlr Sub Hrs 1.00 Sub Labor Amt \$160.00
	Serial #	Appr Hrs 1.00 Appr Labor Amt \$160.00

Notes

Labor

Line# 3	Operation Code 50-134-01-00-001453	Operational Description LP Regulator Hose, Pigtail - Includes Leak Test - LP Gas/LP Gas System/ Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-09-25 16:04:52 :: FIND OUT WHY THE WATER HEATER IS NOT WORKING Gas line to water heater . Turned on the 12v and lp tanks. Checked water levels. Turned on the water pump then the water heater. Turned on the kitchen faucet and waited for the water heater control board to throw a code. And the code that showed up was E1, next Checked the lp line from lp tanks all the way to water heater. Removed the panel under the bathroom sink and found the lp hose was kinked. Went to the underbelly and pulled the lp hose downward to unkink the lp hose. After lp hose was unlinked then turned the kitchen faucet on causing the water heater control board to run properly. No codes showed up, water heater ran as should.	

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

0.60
0.40

Sub Labor Amt \$96.00
Appr Labor Amt \$64.00

Notes

Submitted

Labor Amt \$304.00
Parts & Freight \$0.00
Total \$304.00

Approved

Labor Amt \$256.00
Parts & Freight \$0.00
Total \$256.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.