

aim: C3530822      **Non-Warranty Goodwill Adjustment**      Last Modified by:stutk

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date Of Purcha
530822	71796	11/8/2023	11/8/2023	4YDT31129K3100686	1194	Basden's American RV	600 E Baseline Rd Evansville, IN 47725	160.00	0.00	SA21-414 1/12/20

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
		1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

le code not part of recall  
Component Model: 6020      Component Serial Number: N 17 43

Operation	Description	Srvc advisory	Sub hours	Apv'd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442K	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: Regulator does not fall under recall. Correction: Regulator does not fall under recall.		0.30	0.30	48.00	0.00	1	0.30	Approved

Submitted parts & sublet	0.00	Approved parts & sublet	0.00
Submitted labor & sublet	48.00	Approved labor & sublet	48.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
<b>Total Submitted:</b>	<b>48.00</b>	<b>Total approved:</b>	<b>48.00</b>