

Claim Response

Claim: C3507299

Non-Warranty Goodwill Adjustment

Last Modified bystutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3507299	71804	10/2/2023	10/2/2023	4YDT3112XL3106823		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	160.00	0.00	SA21-414	7/6/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

5218749

Component Model: 6020

Component Serial Number: N 19 10

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: Recall Correction: BRING in unit, inspect LP regulator found date code 19 10, get new regulator and install, ru drop test, pull unit out (Deking/KRV)		0.50	0.50	80.00	0.00	1	0.50	Approved
										5218749

Submitted parts & subLet	28.75	Approved parts & subLet	28.75
Submitted labor & subLet	80.00	Approved labor & subLet	80.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	<u>108.75</u>	Total approved:	<u>108.75</u>