

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1710105
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB0RU042456
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BHS-8
		DEALER RO #	71828
		CLAIM START DATE	10/17/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor				
Line#	Operation Code	Operational Description		
1	20-66-24-00-000658	Entry Door - Exterior/Entry Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-10-17 09:14:07 :: THE MAIN DOOR IS STICKING AND IT IS HARD TO OPEN DOOR LATCH IS HITTING DOOR FRAME ADJUST DOOR LATCH AND FLATTEN DOOR LATCH ON DOOR FRAME			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$48.00
	Notes			
	AUTHORIZED AS REQUESTED			
Labor				
Line#	Operation Code	Operational Description		
2	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-10-17 09:15:05 :: THE WALL TRIM IS LOOSE TRIM CUT TOO LONG STAPLES SHOT THROUGH WALL BOARD REMOVE TRIM TRIM TO FIT, RESTAPEL WALL BOARD, GULE TRIM BACK ON			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$16.00
	Notes			
	AUTHORIZED AS REQUESTED			
Labor				
Line#	Operation Code	Operational Description		
3	40-106-24-11-001253	Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-10-17 09:16:15 :: FIND OUT WHY THE BRAKES ARE BLOWING FUSES \UNIT NOT WIRED RIGHT FOR BRAKES WIRES WITH SHORTS AND LOOSE, 3SHORTS FOUND GET UNDER UNIT AND START TRACEING WIRES AT FROUNT AXEL WIRES FOUND WIRES LOOSE AND SHORTING TO FRAME, REPAIR WIRESAND TEST STILL BLOWING FUSES, TEST BOTH AXELS SEPRETLY AXELS GOOD, TRACE WIRES FOUND WIRE UNDER FREASH TANK PINCHEDTO FRAME AND SHORTING OUT, CUT OUT THAT SETION OF WIRES AND MOVE, REWIRE, TEST BRAKES,			
Model#	Dlr Sub Hrs	3.00	Sub Labor Amt	\$480.00
Serial#	Appr Hrs	3.00	Appr Labor Amt	\$480.00
	Notes			
	AUTHORIZED AS REQUESTED			
Labor				
Line#	Operation Code	Operational Description		
4	10-9-01-00-000158	Stabilizer Jack - Bolt On, each - Frame & Chassis/Levelers, Underbelly/Replace/		

No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-10-17 09:17:11 :: RIGHT REAR JACKS BENT Bolt is bent Bolt is bent turn in PO Get new jack from parts department and remove bent jack, install new jack

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

Labor

Line# 5

Operation Code	Operational Description
40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/ Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-10-17 09:18:28 :: GFI OUT LET WILL NOT TRIP GFI RECEPICAL MISWIRED CHECK RECEPICALS AND FOUND GFI RECEPICAL WITH SUPPLY WIRE ON THE LOAD SIDE OF RECEPICAL, REWIRE RECEPICAL AND TEST

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$48.00

Notes

Submitted	Labor Amt	\$624.00	Approved	Labor Amt	\$624.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$624.00		Total	\$624.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.