



# Warranty Authorization Form

Date: 11/1/2023

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd,  
Evansville, IN 47725  
Ph. (812) 867-5200

### General Information

Pre-Auth #: 49507                      Unit: 7M5FP362XNA006871  
Series: Paradigm                      Model: 2022PAR310RL  
Notes: 10/17 Harlie: Sent to the vendor  
Status: Approved with Modifications

---

### Dealer Information

American RV  
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd,  
Evansville, IN 47725

Requestor: Ben Hoffman  
Return Fax #:  
Email: bhoffman@americanrvcenter.com

---

### Operation Line 1

*Flat Rate Code:* 12003A AWNING - FABRIC - REPLACE - LIPPERT (Photos required)(Data tag required)(LCI auth required)      *Fault Code:* VENDOR

*Serial #:* NA                      *Model #:* V000315206                      *Notes:* 10/19 Harlie: VCB / Lippert will authorize one new awning fabric and 1.5 hours of labor. 10/17 Harlie: Sent to the vendor

*Problem:* FRONT AWNING IS SEPERATING

*Time Requested:* 1.5

*Cause:* awning canvas

*Time Allowed:* 1.5

*Remedy:* brought camper up and rolled out awning,took pictures and filled out sheet to get approved.

*Sublet Repairs:* 0.00

*Part Return Req:* No

*Status:* Approved

---

### Operation Line 2

*Flat Rate Code:* 14019 CABINET - DRAWER - ADJUST                      *Fault Code:* NO PROBLEM FOUND

*Serial #:*                      *Model #:*                      *Notes:* 10/17/23: Danielle -- your dealership was approved to adjust and make repairs to this drawer on PA 40032

*Problem:* KITCHEN DRAWER ON ISLAND TOP DRAWER MOT CLOSING PROPERLY

*Time Requested:* .2

*Cause:* drawer wont shut

*Time Allowed:* 0

*Remedy:* pulled out drawer,the bracket was bent ,pushed back in place.installed drawer back in place and it works like it should.

*Sublet Repairs:* 0.00

*Part Return Req:* No

*Status:* Denied

*Denial Code:*