



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72015
Promised Date:
24 OCT 23

CUSTOMER WORK ORDER

WO #: 72015 (Appointment Date: 16 OCT 2023 - Time: 10:00am)

Customer: 50350 - FISCHER, DAVID -
8127745016

Tag: MATT BH GAVE PS TO ORDER
10-27

Author: BH

Location: 1227 CHECK STATUS WITH
BB

Stock #:

Stock Desc: 2022 TT COACHMEN
CATALINA

Chassis #: 5ZT2CAZB8NX026806

Serial #: 5ZT2CAZB8NX026806

Mileage:

Licence:

Invoice #:

Date In: 16 OCT 23

Promised: 31 OCT 23

Date Sched:

Completed: 26 DEC 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: Tongue Jack light switch missing

CAUSE: FOUND SWITCH MISSING

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
226018	226018 JACK LIGHT SWITCH - LIPPERT	1.00	19.55	19.55

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 51.55

Job #2 - Warranty

COMPLAINT: Vinyl inset in big slide on top is smaller

CAUSE: Removed insert trim that has shrunk. Installed new insert trim.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	16.00

Parts

Part #	Description	Qty	Price	Total
E369	E369 BLACK HD 1" x 25' INSERT TRIM	1.00	8.53	8.53

Subtotal for Job #2: 24.53

Job #3 - Warranty

COMPLAINT: Front bed room front fascia has came off on the bottom

CAUSE: Removed facia. Removed and set Brad nails. Found new screws for facia support. Installed new screws. Secured wall panel and trim to facia support. Installed facia. Cleaned up area.



Customer #: 50350
FISCHER, DAVID

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00
Subtotal for Job #3:			32.00

Job #4 - Internal

COMPLAINT: When the furnace is on and running , water drips from the front bedroom wall / tv wall

CAUSE: Ran furnace through the day. Couldn't replicate issue

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #4:			0.00

Job #5 - Warranty

COMPLAINT: Sliding glass door in front bed room wont move easy like the other one will

CAUSE: Front door came out of track. Both doors are rubbing the bottom track. Adjusted both doors. Set front door in track. Plastic latch for door is broken. Needs a new latch. Pictures on ids.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	48.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts				
Part #	Description	Qty	Price	Total
H527	H527 SLIDING MIRRORED DOOR LATCH	1.00	5.42	5.42
Subtotal for Job #5:				53.42

Job #6 - Warranty

COMPLAINT: Water coming in the washer area you can see paper peeling on the door side wall on top and above the door

CAUSE: Ran sprinkler on the roof for 4 1/2 hours. No water is coming through the ceiling. Panels are peeling like the rest of them. Need to replace panels.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	1,521.60
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	558.40
Z990	MISC LABOUR CODE (EXTERNAL)	BB	99.20
Z990	MISC LABOUR CODE (EXTERNAL)	BB	54.40
Z990	MISC LABOUR CODE (EXTERNAL)	BB	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	166.40

Parts				
Part #	Description	Qty	Price	Total
F100130702	TAPE, SEAM VINYL 1" - 150' ROLL - GA	50.00	0.15	7.50
F100130689	SEAM TAPE - PER FT.	50.00	0.15	7.50
F100285188	3" CABINET STILE	8.00	0.91	7.28
F100285185	STILE, LC 18MM" X 2" X 8' SQUARE CHI	8.00	0.62	4.96





Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAM TAPE	1.00	17.29	17.29
FRT	UPS-STILES	1.00	32.36	32.36

Subtotal for Job #6: 2,636.89

Job #7 - Warranty

Wall paper in middle slide ceiling the paper is coming loose

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: Wall paper coming loose in middle slide side wall under rear window

CAUSE: Wall panels material is peeling off. Need to replace panels around window.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: Wood panel on front slide is loose under bed

CAUSE: Panel came loose. Secured panel with Brad nails.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00

Subtotal for Job #9: 32.00

Job #10 - Internal

COMPLAINT: Water leak under the stove and the fridge

CAUSE: Pressurized water system. Let water heater run until it reached temp. Didn't see any leaks near the water heater or the water pump. It looks like residual anti freeze may have leak out of fill line causing the damage to the stiles.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: In rear bunk area the last ceiling panel is loose

CAUSE: Applied brad nails to ceiling panel as needed. Filled holes with putty.

CORRECTION: .



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	32.00

Subtotal for Job #11: 32.00

Parts Total: 60.74
Labour Total: 2,752.00
Sublet Total: 0.00
Extras Total: 49.65
WORK ORDER TOTAL: 2,862.39

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Dec 2023

W/O: 72015
Promised Date: 31 OCT 23



Customer #: 50350
FISCHER, DAVID

