



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 72042



Customer #: 53902  
BECKER, PAUL B.



## CUSTOMER WORK ORDER

WO #: 72042 (Appointment Date: 18 OCT 2023 - Time: 09:00am)

Customer: 53902 - BECKER, PAUL B. -  
607-341-8744

Tag: PETE FAUCET IS HERE  
10-23-HM

Author: PH

Location: 1025 BH TO CLOSE

Stock #: 11080

Stock Desc: 2024 5W KEYSTONE  
COUGAR SPORT 2100RK

Chassis #: 4YDFCGJ27R2501234

Serial #: 4YDFCGJ27R2501234

Mileage:

Licence:

Invoice #:

Date In: 18 OCT 23

Promised:

Date Sched:

Completed: 25 OCT 23

Warr. Date: 31 JUL 23

### Job #1 - Warranty

COMPLAINT: ENTRY DOOR FRAME IS BENDING WHERE STAIRS LATCH IN

CORRECTION: I FOUND THAT THE STEPS HAD NOT BEEN MOUNTED RIGHT WITH THE THRESHOLD SPACED AWAY FROM THE DOOR FRAME THRESHOLD. THIS WAS KICKING OUT THE LATCH TABS AT THE BOTTOM AND BENDING THE DOOR FRAME. I ADJUSTED THE MOUNTING ON THE STEPS AND IT MOVED THE LATCHES A LITTLE FARTHER BACK. THE STEP LATCHES STILL DID NOT FIT THE DOOR FRAME VERY GOOD. I ADDED A WASHER ON THE BACK SIDE OF THE CROSSBARE AT THE TOP 2 BOLTS. THIS TILTED THE CROSSBARE A LITTLE MORE AND IT SETS GOOD ON THE DOOR FRAME. AFTER THAT, I STRAIGHTENED THE DOOR FRAME AND IT ALL WORKS AS IT SHOULD.

#### Labor

| Code                        | Description          | Mechanic | Total        |
|-----------------------------|----------------------|----------|--------------|
| Z990                        | MISCELLANEOUS REPAIR | GAH      | 96.00        |
| <b>Subtotal for Job #1:</b> |                      |          | <b>96.00</b> |

### Job #2 - Warranty

COMPLAINT: FENDER SKIRT IS COMING LOOSE ON THE DOOR SIDE

CORRECTION: SEALED UP BEHIND FINDER AND PUT NEW SCREWS IN. RESEALED THE AREAS THAT NEEDED IT.

#### Labor

| Code                        | Description          | Mechanic | Total        |
|-----------------------------|----------------------|----------|--------------|
| Z990                        | MISCELLANEOUS REPAIR | GAH      | 16.00        |
| <b>Subtotal for Job #2:</b> |                      |          | <b>16.00</b> |

### Job #3 - Warranty

COMPLAINT: UPPER CABINET ABOVE THE SINK THE TWO DOORS ARE RUBBING TOGEHER

CORRECTION: I ADJUSTED THE CABINET DOORS AS NEEDED.

#### Labor

| Code                        | Description          | Mechanic | Total        |
|-----------------------------|----------------------|----------|--------------|
| Z990                        | MISCELLANEOUS REPAIR | GAH      | 16.00        |
| <b>Subtotal for Job #3:</b> |                      |          | <b>16.00</b> |

### Job #4 - Warranty

COMPLAINT: KITCHEN FAUCET LEAKS AT THE HEAD WHEN IT IS PULLED DOWN

CORRECTION: I RAN WATER MANY TIMES AND FOUND THAT THE UPPER PART OF THE SPRAYER



WAS LEAKING WHEN HELD AT AN ANGLE. I TOOK THE SPRAYER APART AND ALL I COULD FIND IS THE RUBBER WASHER WAS LEAKING WHEN THE SPRAYER WAS PULLED TO THE SIDE. CAN NOT TIGHTEN THE FITTING ANY MORE THEN IT IS. FAUCET NEEDS REPLACED.

**Labor**

| Code | Description          | Mechanic | Total |
|------|----------------------|----------|-------|
| Z990 | MISCELLANEOUS REPAIR | GAH      | 0.00  |
| Z990 | MISCELLANEOUS REPAIR | GAH      | 80.00 |
| Z990 | MISCELLANEOUS REPAIR | GAH      | 0.00  |

**Parts**

| Part # | Description                                                                                    | Qty  | Price | Total |
|--------|------------------------------------------------------------------------------------------------|------|-------|-------|
| 635088 | Faucet - Kitchen - Pull-Out - Single Hole<br>- Lever Handle - Nickel B-Head -<br>K8196B-1-NK-L | 1.00 | 52.34 | 52.34 |

**Other Services**

| Code | Description | Qty  | Price | Total |
|------|-------------|------|-------|-------|
| FRT  | FREIGHT     | 1.00 | 22.67 | 22.67 |

**Subtotal for Job #4: 155.01**

Parts Total: 52.34  
 Labour Total: 208.00  
 Sublet Total: 0.00  
 Extras Total: 22.67  
**WORK ORDER TOTAL: 283.01**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 25 Oct 2023

Customer #: 53902  
 BECKER, PAUL B.

