

Approved date 10/31/2025:

Basden's American RV
600 E Baseline Rd
Evansville, IN 47725

Root Cause Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction

Complaint: DOOR/SLIDE REAR WINDOW LEAKING WHEN
LOOKING AT THE COUCH TO THE LEFT
Cause: Window leak
Correction: Remove window. Put on new foam tape. Put window
back. Silicone top of window

KRV – Labor time adjusted allowing for proper repair procedure to be performed.

Complaint: DOORSIDE SLIDE ROOM REAR WINDOW LEAKING WHEN LOOKING AT THE COUCH ITS TOO THE

Cause:Window leak
Correction:Remove couch. Remove the valance. Remove window. Remove outlet and light switch. Remove trim. Remove wall panel. Put a new wall panel. Put on new trim. Put new foam tape on widow. Put window back. Silicone on top of window

6.00

Our paper claims only use one pre-authorization number per warranty claim for

1. Complete a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the