



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72247
Promised Date:
29 NOV 23

CUSTOMER WORK ORDER

WO #: 72247 (Appointment Date: 06 NOV 2023 - Time: 02:30pm)

Customer: 53803 - SCHMITT, DYLAN C. Stock #: 11243

- 812-430-8482

Tag:

Author: BJW

Location: 1207 CHECK STATUS WITH
BB

Stock Desc: 2023 TT COACHMEN

CATALINA SUMMIT SERIES 231MKS

Chassis #: 5ZT2CAMB6PU041011

Serial #: 5ZT2CAMB6PU041011

Mileage: 0

Licence:

Invoice #: 399302

Date In: 06 NOV 23

Promised: 30 NOV 23

Date Sched:

Completed: 30 NOV 23

Warr. Date: 29 JUN 23

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: winterized unit and did everything on sheet,

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SLIDE SEALS ON THE SLIDE HAVE SLID DOWN

CAUSE: inserts on slideroom

CORRECTION: inserts were sliding down not slide seals, took old ones out and installed new inserts.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	48.00

Subtotal for Job #2: 48.00

Job #3 - Internal

COMPLAINT: CUSTOMER ADVISES THAT ON A PREVIOUS VISIT, WE INSTALLED FOAM BLOCKS UNDER THE SLIDE ROOM AND ONE OF THE BLOCKS HAS COME OUT.

CAUSE: foam blocks missing

CORRECTION: used seals to seal around floor so it seals and no day light.



Customer #: 53803
SCHMITT, DYLAN C.





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER ADVISED THAT THERE IS BUBBLES UNDER THE WALL PAPER IN THE FRONT SIDE OF THE SLIDE ROOM.

CAUSE: paneling bubbling

CORRECTION: took pictures of paneling in slideroom, under kitchen window and bedroom, filled out sheet for ben to get approved.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	764.80
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	369.60
Z990	MISC LABOUR CODE (EXTERNAL)	BB	625.60

Parts				
Part #	Description	Qty	Price	Total
F100130689	SEAM TAPE - PER FT.	30.00	0.15	4.50
Subtotal for Job #4:				1,924.50

Job #5 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE WALLPAPER UNDER THE DOOR SIDE WINDOW IN THE BEDROOM IS WRINKLING.

CAUSE: wallpaper

CORRECTION: see job 4 ben wants on 1 job.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Subtotal for Job #5:			0.00

Parts Total:	4.50
Labour Total:	1,968.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	1,972.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Dec 2023

