

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72318
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 54079 - KASEY IGLEHEART
Address: 8503 E 100 N CANNELBURG, IN

47519

Phone: 812-698-9297

Stock Number: 11262 - 2023 CHEROKEE GREY WOLF 29TE 4X4TCKE23PX161612

VIN: 4X4TCKE23PX161612 HIN:

SER#: 4X4TCKE23PX161612

Mileage: 0

Work Order Comp: 18 DEC 23

Auth. No:

Dealer #:

Warr. Date: 05 OCT 23

Work Order Date: 14 NOV 23

Inv #: 399520

WO # Job # Description JOB INFORMATION

72318 3 BLIND KEEPS FALLING OFF THE WALL RIGHT ABOVE THE COUCH
Blind got tethered and caught in the pull bar of blind
Inspected how the blind mounts but didn't find any broken parts.
Clipped the blind back up, pulled on blind aggressively to
simulate it coming undone from it mount. Couldn't get blind to
fall down. When the blind was hanging down one the left side it
caused the right side to catch and tether the fabric. Put in po
fornew blind. Measurements and pictures

72318 1 FRESH TANK IS LEAKING UNDER UNIT
Fresh tank crack
Got the garden hose and filled the fresh tank 1/3 full. Inspected
around the underbelly for water leaks. Took pictures of the fresh
tank leaking before the underbelly was pulled down. Pulled down
the underbelly and found what appears to be a crack in the fresh
tank. Circled the leak with a blue sharpie. Took picture of
numbers on the tank. Drained the water from fresh tank. Put the
underbelly backup. Waiting on warranty. Received new fresh tank.
Removed the underbelly below the fresh tank. Disconnected the
water lines and sensors. Unbolted the bolts holding in the tank.
Dropped out the fresh tank. Placed and bolted in new fresh tank
in the underbelly. Hooked up the water lines and sensors. Filled
fresh tank 2/3full to check for any leaks. No leaks. Took
pictures. Drained the fresh tank since it was winterized.

72318 2 FRONT COMPARTMENT DOOR LATCH IS BENT

Claim : 72318

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
          Manuel lock was loose on front compartment door.
          Opened the front compartment door and inspected the latches.
          Couldn't find a bent latch but did find the manual latch loose.
          Tightened the nut on the backside of the latch. Inspected the key
          locking latch but found no problem. Took picture

```

```

*****
Part No    Job#   Description      PARTS      Qty      Price      Total
*****
F100141513    3   SHADE, 64" X 24" ZEBRA SHADE / 20  1.00      75.05      75.05
F100257740    1   TANK, FRESH WATER W/ PROBES, 40 G  1.00     100.04     100.04

```

```

*****
Lab Code   Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990        3   MISC LABOUR CODE (EXTERNAL)          0.20     160.00      32.00
Z990        3   MISC LABOUR CODE (EXTERNAL)          0.00     160.00       0.00
Z990        1   MISC LABOUR CODE (EXTERNAL)          2.30     160.00     368.00
Z990        1   MISC LABOUR CODE (EXTERNAL)          0.40     160.00      64.00
Z990        1   MISC LABOUR CODE (EXTERNAL)          0.30     160.00      48.00
Z990        2   MISC LABOUR CODE (EXTERNAL)          0.10     160.00      16.00

```

```

*****
Excode     Job#   Description      EXTRAS      Qty      Price      Total
*****
FRT         3   UPS-SHADE          1.00     105.74     105.74
FRT         1   FREIGHT FOR FRESH TANK  1.00     145.65     145.65

```

```

Parts Total:      175.09
Labour Total:     528.00
Sublet Total:       0.00
Extras Total:     251.39

```

>>>> Claim Total: 954.48

Customer Signature: _____

Date: _____