

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1741600
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKE23PX161612
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT29TE
KASEY IGLEHEART		DEALER RO #	72318
8503 E 100 N		CLAIM START DATE	11/16/2023
Cannelburg, IN 47519		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	10/05/2023	WARRANTY EXPIRATION DATE	10/05/2024

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-136-01-00-001496	Fresh Water Tank - Below Floor - Plumbing/Fresh Water Supply/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-11-16 12:05:52 :: FRESH TANK IS LEAKING UNDER UNIT Fresh tank crack Got the garden hose and filled the fresh tank 1/3 full. Inspected around the underbelly for water leaks. Took pictures of the fresh tank leaking before the underbelly was pulled down. Pulled down the underbelly and found what appears to be a crack in the fresh tank. Circled the leak with a blue sharpie. Drained the water from fresh tank. Put the underbelly backup. Waiting on warranty.			
Model#	Dlr Sub Hrs	5.00	Sub Labor Amt	\$800.00
Serial#	Appr Hrs	3.00	Appr Labor Amt	\$480.00
	Notes			
	3.0 per labor code			

Labor

Line# 2	Operation Code	Operational Description		
	20-69-01-00-000703	Hold Back Latch, Catch, or Magnet - Exterior/Compartment Doors/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-11-16 12:07:29 :: FRONT COMPARTMENT DOOR LATCH IS BENT Manuel lock was loose on front compartment door. Opened the front compartment door and inspected the latches. Couldn't find a bent latch but did find the manual latch loose. Tightened the nut on the backside of the latch. Inspected the key locking latch but found no problem. Took picture			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$16.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	30-99-01-00-001012	Mini-Blind - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-11-16 12:08:45 :: BLIND KEEPS FALLING OFF THE WALL RIGHT ABOVE THE COUCH Blind got tethered and caught in the pull bar of blind Inspected how the blind mounts but didn't find any broken parts. Clipped the blind back up, pulled on blind aggressively to simulate it coming undone from it mount. Couldn't get blind to fall down. When the blind was hanging down one the left side it caused the right side to catch and tether the fabric. Put in po fornew blind. Measurements and pictures			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

Submitted	Labor Amt	\$848.00	Approved	Labor Amt	\$528.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$848.00		Total	\$528.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	