



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72418
Promised Date:
24 JAN 24



Customer #: 1000
BASDENS AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 72418

Customer: 1000 - BASDENS AMERICAN

RV -

Tag:

Author: BH

Location: 0126 BH TO CLOSE

Stock #: 11291

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC9RK007117

Serial #: 5ZT2CAEC9RK007117

Mileage: 0

Licence:

Invoice #:

Date In: 27 NOV 23

Promised: 31 JAN 24

Date Sched:

Completed: 26 JAN 24

Warr. Date:

Job #PDITT - Internal

Transferred to BAS*72593 on 27 DEC 23

Estimate amount was 0.00

PDINTT SMALL PDI 2 HR MAX

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C

Subtotal for Job #PDITT: 0.00

Job #WINTER - Internal

Transferred to BAS*72593 on 27 DEC 23

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: WALL PANEL ABOVE BUNK IS COMING LOOSE

CORRECTION: AFTER REMOVING THE TAPE FROM THE WALL,
I FOUND THAT THE WALL HAD NOT BEEN
STAPLED ON THE REAR PANEL. I ADDED



STAPLES AND REINSTALLED THE TAPE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: WATER IS COMING IN THE FRONT CAP AREA
NEAR THE TV BOOSTER

CORRECTION: I REMOVED THE
BOOSTER AND WIFI PANEL BECAUSE I SEEN
WATER SPOTS ON THE STORAGE DOOR AT THE
BED. I ALSO FOUND THAT THE BOOSTER HAD
WAS SPOTS ON THE BACK SIDE OF IT. I NEED
TO REPLACE THE BOOSTER. I USED A
MOISTURE METER TO FIND OUT WHAT PART OF
THE CEILING WAS THE MOST WET. I FOUND
THAT UNDER THE SOLAR PORTS ON THE ROOF
HAD THE MOST MOISTURE. I STARTED TO
REMOVE THE SOLAR PORT AND FOUND THAT IT
WAS SPLIT ALL THE WAY ACROSS THE MIDDLE
OF IT. I NEED A NEW SOLAR PORT FOR THE
ROOF AND A NEW STORAGE DOOR BY THE BED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	80.00

Parts

Part #	Description	Qty	Price	Total
F100282515	TOP, HINGED NIGHTSTAND 34 X 12 1/4 C	1.00	26.81	26.81
F100334694	PLATE, CABLE ENTRY W/ RED & BLACK	1.00	14.18	14.18
C01298161	WALL PLATE, POWER INJECTOR SWITCH W/	1.00	12.56	12.56

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - ALL PARTS	1.00	17.27	17.27

Subtotal for Job #2: 230.82

Job #3 - Warranty

COMPLAINT: SEALER ON THE WATER HEATER IS NOT INSTALLED RIGHT

CORRECTION: I REMOVED THE OLD SEALER FROM THE WATER HEATER AND RESEALED THE
LOWER PART OF THE OUTSIDE TRIM TO KEEP UNIT FROM LEAKING.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	32.00

Subtotal for Job #3: 32.00

Job #4 - Warranty

COMPLAINT: WATER HEATER FITTING LEAKING ON THE BACK OF IT

CORRECTION: I FOUND THE WATER HEATER BRASS FITTINGS HAD NOT BEEN TIGHTENED.
WHEN WATER HEATER WAS UNDER PRESSURE THE FITTING STARTED LEAKING DOWN THE
BACK OF THE WATER HEATER. I REMOVED THE FITTINGS TO ADD THREAD TAPE TO THE
FITTINGS. I REINSTALLED THE FITTINGS AND TIGHTENED THEM DOWN. AFTER HOOKING UP THE

W/O: 72418
Promised Date: 31 JAN 24



Customer #: 1000
BASDENS AMERICAN RV,



WATER LINES, I PUT PRESSURE TO THE WATER HEATER AGAIN. IT IS NO LONGER LEAKING.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	64.00
Subtotal for Job #4:			64.00

Parts Total:	53.55
Labour Total:	288.00
Sublet Total:	0.00
Extras Total:	17.27
WORK ORDER TOTAL:	358.82

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Jan 2024

W/O: 72418
Promised Date: 31 JAN 24



Customer #: 1000
BASDEN'S AMERICAN RV,

