

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1775307
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXNBXRS047006
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT243FKS
		DEALER RO #	72427
		CLAIM START DATE	12/27/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	30-102-24-00-001094	Operational Description
		Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-12-27 14:40:12 :: LEFT OF STOVE WOOD DAMAGED Filled holes with wood putty and used colored marker to match color.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$16.00
Serial#	Appr Hrs	Appr Labor Amt
	0.10	\$16.00
Notes		

Labor

Line# 2

Operation Code	30-91-24-00-000923	Operational Description
		Furniture - Sofa or Chairs - Interior/Living Quarters, Sofa, Chair/Repair/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-12-27 14:41:26 :: STAIN ON COUCH Checked stain. Looks like thread sealer compound. Used mineral spirits to remove stain.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$16.00
Serial#	Appr Hrs	Appr Labor Amt
	0.10	\$16.00
Notes		

Labor

Line# 3

Operation Code	30-101-02-00-001076	Operational Description
		Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-12-27 14:42:06 :: LIVING TO BATHDOOR RIGHT SIDE NOT STRAIGHT WITH DOOR FRAME Bottom hinge is not mounted in correct position. Removed screws from door frame mounting. Repositioned bottom hinge on door frame and remounted in correct position.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$32.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$32.00
Notes		

Labor

Line# 4

Operation Code	30-101-02-00-001076	Operational Description
		Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-12-27 14:42:44 :: CABINET DOOR NEXT TO ENTRY DOOR DAMAGED Covered damaged area with matching putty.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$32.00

Serial#

Notes

Appr Hrs

0.20

Appr Labor Amt

\$32.00

Labor

Line# 5

Operation Code

50-134-01-00-003645

Operational Description

Outside Grill LP Hose with Valve - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-12-27 14:43:41 :: LP HOSE MISSING FOR OUTSIDE GRILL GET NEW HOSE FOR GRILL

Model#

Dlr Sub Hrs

0.05

Sub Labor Amt

\$8.00

Serial#

Appr Hrs

0.05

Appr Labor Amt

\$8.00

Notes

Submitted	Labor Amt	\$104.00	Approved	Labor Amt	\$104.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$104.00		Total	\$104.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.