



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72616
Promised Date:
24 JAN 24

CUSTOMER WORK ORDER

WO #: 72616

Customer: 50350 - FISCHER, DAVID -
8127745016

Tag: BH - PARTS ORDERED 1-15-24

Author: BH

Location: 0130 CHECK PREAUTH

Stock #:

Stock Desc: 2022 TT COACHMEN
CATALINA

Chassis #: 5ZT2CAZB8NX026806

Serial #: 5ZT2CAZB8NX026806

Mileage:

Licence:

Invoice #: 400281

Date In: 30 DEC 23

Promised: 31 JAN 24

Date Sched:

Completed: 24 JAN 24

Warr. Date:

Job #1 - Warranty

COMPLAINT: THE WOOD PANEL TO THE LEFT AND RIGHT OF THE SLIDE ROOM ARE NOT FIXED

CAUSE: Panels.

CORRECTION: Already did on another work order.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: BATHROOM CABINET WOOD IS DAMAGED AND NEEDS FIXED

CAUSE: Stiles

CORRECTION: Remove toilet. Remove cabinet door and access panel. Remove damaged cabinet front. Remove cabinet front to the left of the sink. Build two new frames and install. Put door back and panel. Silicone around bottom. Put toilet back.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Parts

Part #	Description	Qty	Price	Total
F100285187	2.5" STILE	16.00	0.87	13.92
F100285185	STILE, LC 18MM" X 2" X 8' SQUARE CHI	16.00	0.62	9.92
6631	STILE, LC 18MM" X 5-1/4" X 8' SQUARE	16.00	1.52	24.32

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	31.78	31.78

Subtotal for Job #2: 79.94

Job #3 - Warranty

COMPLAINT: THE CABINET DOOR IN THE BUNKROOM CAME OFF THE HINGES

CAUSE: Door



Customer #: 50350
FISCHER, DAVID



CORRECTION: Remove door. Put plugs in screw holes. Mount door back.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: TO THE RIGHT OF THE STOVE THE WOOD IS DAMAGED

CAUSE: Stiles

CORRECTION: Remove water heater access panel. Remove stove and cut 12 v wires. Remove shelf below stove. Remove damaged 3 1/4 stile. Cut and install new stile. Staple back braces. Wire up stove and put back. Put panel back. Do drop test on lp. Remove cabinet doors above converter. Remove customers goods and put them in boxes. Remove four shelves. Remove converter. Remove outlet. Unscrew cabinet front from wall. Pry cabinet front from shelves. Cut off staples on 3/4" supports. Remove damaged stile. Cut new stile. Staple back on supports. Install front back and staple. Remove cabinet door. Remove stereo. Remove outlet. Remove both shelves. Remove damage stile. Cut new stile. Install. Put door and shelves back. Put radio back.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	440.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	560.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	520.00
Subtotal for Job #4:			1,600.00

Job #5 - External

INSTALL A SCREEN AND A METAL SCREEN ON THE ENTRY DOOR

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts Part #	Description	Qty	Price	Total
8826	Aupar Aluminum Alloy RV Entry Screen	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
FRT	UPS-SCREEN	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Parts Total:	48.16
Labour Total:	1,600.00
Sublet Total:	0.00
Extras Total:	31.78
WORK ORDER TOTAL:	1,679.94

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 72616
Promised Date: 31 JAN 24



Customer #: 50350
FISCHER, DAVID

