



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72657



CUSTOMER WORK ORDER

WO #: 72657
Customer: 1000 - BASDEN'S AMERICAN RV -
Tag:
Author: BH
Location: 0131 CHECK WORK

Stock #: 11300
Stock Desc: 2024 TT COACHMEN APEX 243FKS
Chassis #: 5ZT2CXNBXRS047006
Serial #: 5ZT2CXNBXRS047006
Mileage: 0
Licence:

Invoice #:
Date In: 08 JAN 24
Promised:
Date Sched:
Completed: 09 JAN 24
Warr. Date:

Job #1 - Warranty

COMPLAINT: BATHROOM ENTRY DOOR HARD TO SHUT

CAUSE: Latch is dragging across the stricker plate

CORRECTION: Inspected the bathroom entry door. Took a lot of effort to close the bathroom entry door. Found the latch on the door was dragging across the stricker plate and the door has a bow. Adjusted the plate, used pieces of wood to help take out some of the bow. Such as placing a block of wood at top and bottom of door then pushing in the middle. Now bathroom entry door closes with ease and is latching properly.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	48.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Subtotal for Job #1:			48.00

Job #2 - Warranty

COMPLAINT: COAT HANGER IN BATHROOM LOOSE

CAUSE: Screw hole is stripped

CORRECTION: Took pictures of the coat hanger loose from the wall. Only had to remove 1 screw from the wall as the other screw was not holding. Pulled both screws out then move the coat hanger a 1/4 inch. Screwed in the coat hanger back into the wall.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	16.00
Subtotal for Job #2:			16.00

Parts Total:	0.00
Labour Total:	64.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	64.00

Customer #: 1000
BASDEN'S AMERICAN RV,

