

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1788662
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXR4RS046850
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT264RKS
		DEALER RO #	72658
		CLAIM START DATE	01/12/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	10-12-01-00-000260	Black or White Plastic Slide Out Skis - Frame & Chassis/Slide Out System - Lippert/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-12 14:17:35 :: BACK OF SLIDE SKI IS TORN BACK OF SLIDE SKI IS TORN Took pictures of slide out rear slide ski. Ski has a notch in it and needs replaced. Removed bottom trim and tried to get slide ski off. Parts of slide out will need to be removed to replace ski. Remount bottom trim. Turned in parts request. Moved unit back on lot.			
Model#		Dlr Sub Hrs	4.00	Sub Labor Amt \$640.00
Serial#		Appr Hrs	3.00	Appr Labor Amt \$480.00
	Notes			
	Dealer has requested more time than what is normally approved for this repair. Forest River will allow 3.0 hr for this repair. If you have questions about the approved time, please contact me directly to discuss.			

Labor

Line# 2	Operation Code	Operational Description		
	10-9-01-16-000173	Bumper, Welded - Frame & Chassis/Levelers, Underbelly/Replace/Structure		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-12 14:19:13 :: SCRATCH ON TOP RIGHT SIDE OF BUMPER SCRATCH ON TOP RIGHT SIDE OF BUMPER Took picture. Turned in parts request for a new bumper. WELD ON NEW BUMMPER			
Model#		Dlr Sub Hrs	2.00	Sub Labor Amt \$320.00
Serial#		Appr Hrs	1.00	Appr Labor Amt \$160.00
	Notes			
	can this be sanded down and painted. If not please provide chassis tag on the frame "LD" PIC UPLOADED			
	Please answer my question and thank you for the tag			
	no it can not be sanded			
	no vcb			

Labor

Line# 3	Operation Code	Operational Description		
	30-101-01-00-001076	Hinged Passage Door - Interior/Interior Doors/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-12 14:20:28 :: SCRATCH AT THE TOP OF BEDROOM DOOR SCRATCH AT THE TOP OF BEDROOM DOOR Took picture and turned in parts request for new door. NEED TO REPLACE THE DOOR			
Model#		Dlr Sub Hrs	0.50	Sub Labor Amt \$80.00
Serial#		Appr Hrs	0.50	Appr Labor Amt \$80.00

Notes

Submitted

Labor Amt	\$1,040.00
Parts & Freight	\$0.00
Total	\$1,040.00

Approved

Labor Amt	\$720.00
Parts & Freight	\$0.00
Total	\$720.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.