

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 72659
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11270 - 2024 SPRINGDALE 200RLC 4YDTSGJ29R7100132

VIN: 4YDTSGJ29R7100132 HIN:

SER#: 4YDTSGJ29R7100132

Mileage: 0

Work Order Comp: 15 JAN 24

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 08 JAN 24

Inv #: 400104

WO # Job # Description JOB INFORMATION

72659 1 BATHROOM ROOD SLIDING DOOR IS OFF THE HINDGES
Hinge latch wasn't holding and door handle catching the door
frame.
Inspected the bathroom door hinge, found the latch that holds the
door to the rollers was off. Removed the fabric trim above the
sliding bathroom door, found the latch wasn't tight enough to
keep itself closed. Added more twist to latch, now it has a
tighter fit. After fixing the latch noticed the bathroom door
handle was catching the plastic door frame when trying to close
the door. Found the the wall has a bow to it and prevents the
door from closing. Removed the screws from the slide track then
moved the track away from the wall so door handle would clear.
Checked the door for clearance, now handle doesn't catch when
closing the bathroom door.

72659 3 UNDER THE KITCHEN SINK THE CABINET DOORS RUB
Cabinet doors under the sink was rubbing
Inspected the cabinet doors as they were rubbing when opening and
closing. When opening one or the other door was causing the
opposite door to open. Got some cardboard and placed between the
doors then pushed them closed. This moved the hinges very little.
Now the doors don't rub when opening or closing.

72659 4 COUCH TO CLOSE TO THE WALL AND WONT FOLD
Sofa doesn't have enough room to fold flat.
Inspected the sofa and found that it doesn't have enough room

Claim : 72659

 WO # Job # Description JOB INFORMATION

behind it to fold flat. Removed the screws holding sofa to wall.
 There is about a 3inch difference that the sofa needs to lay
 flat. Cut pieces of wood and placed behind the sofa. Screwed
 those pieces of wood to the wall then screwed the sofa to the
 wood. Checked the sofa for clearance to fold flat.

72659 5 MARKS ON THE BACK OF THE COUCH
 Rub markings on back of sofa from hitting the wall
 Inspected the back of the sofa for damage, found rub marks were
 sofa was hitting the wall. Put in po for new sofa.

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISCELLANEOUS REPAIR		0.60	160.00	96.00
Z990	3	MISCELLANEOUS REPAIR		0.10	160.00	16.00
Z990	4	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	4	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	4	MISCELLANEOUS REPAIR		0.30	160.00	48.00
Z990	5	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	5	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	5	MISCELLANEOUS REPAIR		0.20	160.00	32.00

Parts Total: 0.00
 Labour Total: 192.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 192.00

Customer Signature: _____

Date: _____