

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1795662
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEVB9RW028659
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET298FDS-320
		DEALER RO #	72680
		CLAIM START DATE	01/22/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-22 13:26:08 :: OUTSIDE KITCHEN WOOD RIGHT SIDE DAMAGED OUTSIDE KITCHEN WOOD RIGHT SIDE DAMAGED Cabinet wood was damaged Wood has been mounted with screws with heads countersunk. Then screw heads were covered with matching putty. See if matching tape can be ordered to cover wood strip. Received the replacement sticky paper. Cut a piece to size then set in place. Pilled the sticky back and pressed the paper along the cabinet wood. Trimmed with silicone.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$80.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$80.00
	Notes			
	repair stile and cover with matching tape			

Labor

Line# 2	Operation Code	Operational Description		
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-22 13:27:02 :: BATHTO BED DOOR TRIM RIGHT SIDE IS COMING OFF BATH TO BED DOOR TRIM RIGHT SIDE IS COMING OFF Trim is too long and bowed out. Brad nails that secures trim to wall have pulled thru trim. Made all old brad nails flush. Shortened trim at bottom and reattached to wall. Filled all nail holes with matching putty.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$32.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-01-22 13:27:36 :: WALL PAPER IN BATHROOM WHERE THE WASHER GOES THE WALL IS DAMAGED SEE BEN IF YOU CANT FIND IT WALL PAPER IN BATHROOM WHERE THE WASHER GOES, THE WALL IS DAMAGED. SEE BEN IF YOU CAN'T FIND IT. Wall paper was torn in one spot. Straightened paper and reattached.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$32.00
	Notes			

Labor
Line# 4

Operation Code
30-102-01-00-001096

Operational Description
Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/
Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-01-22 13:28:20 :: TRIM LOOSE IN CABINET WHERE THE
WASHER GOES LOOSE TRIM IN CABINET WHERE WASHER GOES Reattached vertical trim washer area with
brad nails. Filled all nail holes with matching putty.

Model#
Serial#

Dlr Sub Hrs
Appr Hrs

0.20
0.20

Sub Labor Amt \$32.00
Appr Labor Amt \$32.00

Notes

Submitted	Labor Amt	\$176.00	Approved	Labor Amt	\$176.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$176.00		Total	\$176.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.