



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72682
Promised Date:
24 JAN 24



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 72682

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag: BH - PARTS ARE HERE 1-18

Author: BH

Location: 0129 BH TO CLOSE

Stock #: 11192

Stock Desc: 2023 TT COACHMEN

CATALINA SUMMIT SERIES 261BH

Chassis #: 5ZT2CARB5PU041736

Serial #: 5ZT2CARB5PU041736

Mileage: 0

Licence:

Invoice #:

Date In: 10 JAN 24

Promised: 31 JAN 24

Date Sched:

Completed: 26 JAN 24

Warr. Date:

Job #1 - Warranty

COMPLAINT: DOOR SIDE REAR DECAL (COACHMAN) THE M IS DAMAGED

CAUSE: decal

CORRECTION: took pictures of decal and filled out sheet to replace.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
F100297476	DECAL, COACHMEN W/ PETE 26.5" BLACK/WHT "3"	1.00	5.20	5.20

Subtotal for Job #1: 37.20

Job #2 - Warranty

COMPLAINT: DOOR SIDE REAR COMPARTMENT WALL DAMAGED

CAUSE: wall board

CORRECTION: installed a piece of trim to cover defect.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	16.00

Subtotal for Job #2: 16.00

Job #3 - Warranty

COMPLAINT: DOOR SIDE BEDROOM WALL COMING LOOSE

CAUSE: bedroom wall

CORRECTION: took off seam tape and restapled, then got new seam tape and installed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	16.00



Subtotal for Job #3: 16.00

Job #4 - Warranty

COMPLAINT: UNDER BED ODS PANEL OFF

CAUSE: bed panel

CORRECTION: stapled panel back in place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	16.00

Subtotal for Job #4: 16.00

Job #5 - Warranty

COMPLAINT: THE MAIN CONTROL PANEL DOES NOT WORK

CAUSE: THE PANEL FAILED SWAPED PANEL WITH NEW A DIFFERENT ONE AND WORKS FINE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
F100319232	MONITOR PANEL, C 1A-0S-3T 2021136743 GOES TO 20TH 26TH 174BH 174RB 184DBK 192BH 221R	1.00	67.79	67.79

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT FOR CONTROL PANEL	0.00	0.00	0.00

Subtotal for Job #5: 99.79

Job #6 - Warranty

COMPLAINT: OUTSIDE TRIM IS BUSTED ON ENTRY DOOR

CAUSE: rigid entry door cover

CORRECTION: cover was popped out and broken, need to order new piece.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
F100306580	SCREW COVER , ENTRY DOOR , HARD PLASTIC U CHANNEL 80"	8.00	0.14	1.12

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT FOR SCREW COVER	0.00	0.00	0.00

Subtotal for Job #6: 33.12

W/O: 72682
Promised Date: 31 JAN 24

Parts Total:	74.11
Labour Total:	144.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	218.11

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 26 Jan 2024

Customer Signature : _____



Customer #: 1000
BASDENS AMERICAN RV,

