

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1804201
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXLBXR016951
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	224 / 224
OWNER INFORMATION		ITEM #	AAPT221RLS
		DEALER RO #	72761
		CLAIM START DATE	01/30/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code 30-92-01-00-001154

Operational Description Sink Cover - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-01-30 15:26:11 :: SINK COVER IS WARPED, WATER DAMAGE SINK COVER IS WARPED, WATER DAMAGE Took pictures of sink cover. (23 3/8 X 13 3/8 x5/8). Turned in parts request for a new sink cover.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$16.00
Serial#	Appr Hrs	0.00	Appr Labor Amt \$0.00

Notes
This is a parts only code

Labor

Line# 2

Operation Code 20-66-02-00-000664

Operational Description Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-01-30 15:31:53 :: ENTRY DOOR NEEDS ADJUSTED3 ENTRY DOOR NEEDS ADJUSTED Checked closing of entrance door. Found that shipping wedge was still in place on bottom of door. Removed wedge and glue from door. Door now closes ok.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$48.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$48.00

Notes

Labor

Line# 3

Operation Code 60-136-01-00-003266

Operational Description In-Line Check Valve - Back Flow Preventer - Plumbing/Fresh Water Supply/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-01-30 15:32:37 :: CITY WATER CHECK VALVE BAD CITY WATER CHECK VALVE IS BAD Water leaks out city water connection when running water pump. Removed city water connection. Check valve is bad. Cleaned surface around mounting flange. Installed new city water connection. Checked water line connection for leak. None found. Remounted connection and sealed.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$80.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$80.00

Notes

Labor

Line# 4

Operation Code 30-101-02-00-001076

Operational Description Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-01-30 15:46:58 :: BATHROOM DOOR WILL NOT LATCH

CLOSED BATHROOM DOOR WILL NOT LATCH CLOSED Door plunger is not hitting latch plate hole. Trimmed out frame material and relocated latch plate to align with door plunger.

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$32.00

Serial# Appr Hrs 0.20 Appr Labor Amt \$32.00

Notes

Submitted	Labor Amt	\$176.00
	Parts & Freight	\$0.00
	Total	\$176.00

Approved	Labor Amt	\$160.00
	Parts & Freight	\$0.00
	Total	\$160.00

DEALER _____ DATE _____

SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE
All repairs described have been inspected and are satisfactory.