

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1807271
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEUB6RW029088
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET288BHDS-320
		DEALER RO #	72788
		CLAIM START DATE	02/02/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-58-24-00-000813	Operational Description Lower Radius Metal, per piece - Exterior/Metal, Aluminum Siding/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-02-02 09:45:18 :: THERE IS GLUE ON DOORSIDE FRONT BOTTOM BLACK METAL glue on j wrap took mineral spirits and cleaned off of j wrap.	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$32.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$32.00
	Notes remove silicone and clean lower radius metal	

Labor

Line# 2	Operation Code 20-69-02-17-000708	Operational Description Compartment Door Lock or Slam Latch - Exterior/Compartment Doors/Adjust/Latch
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-02-02 09:46:06 :: DOOR SIDE FRONT COMPARTMENT DOOR WONT LATCH WHEN HINGED UP latch moved latch up just abit to shut.	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$32.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$16.00
	Notes correct code for hold back is 20-69-01-00-000703 = 0.1	

Labor

Line# 3	Operation Code 20-66-02-00-000664	Operational Description Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-02-02 09:46:48 :: REAR ENTRY DOOR WONT LATCH WHEN SHUT FROM INSIDE rear entry door adjusted catch .	
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt \$48.00
Serial#	Appr Hrs 0.10	Appr Labor Amt \$16.00
	Notes see correct code 30-101-02-00-001077; adjust entry door striker plate (2 screws) 30-101-02-00-001077 = 0.10	

Labor

Line# 4	Operation Code 70-472-01-00-003692	Operational Description Suburban Elite Griddle Top Only - Appliances/Cooktop/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-02-02 09:48:09 :: SIDE TABLE AND GRIDDLE BRACKETS IS MISSING need parts to be able to hold grill up	
Model#	SOP1003A	Dlr Sub Hrs 0.20
		Sub Labor Amt \$32.00

Serial# 232802478N

Appr Hrs

0.10

Appr Labor Amt \$16.00

Notes

missing; install griddle brackets = 0.10

Submitted

Labor Amt	\$144.00
Parts & Freight	\$0.00
Total	\$144.00

Approved

Labor Amt	\$80.00
Parts & Freight	\$0.00
Total	\$80.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.