



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72788



CUSTOMER WORK ORDER

WO #: 72788

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0220 CHECK PARTS

Stock #: 11321
Stock Desc: 2024 TT COACHMEN
FREEDOM EXPRESS 288BHS
Chassis #: 5ZT2FEUB6RW029088
Serial #: 5ZT2FEUB6RW029088
Mileage: 0
Licence:

Invoice #:
Date In: 01 FEB 24
Promised:
Date Sched:
Completed: 16 FEB 24
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C
Z990	WINTERIZE UNIT	DGH	N/C
Z990	WINTERIZE UNIT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THERE IS GLUE ON DOORSIDE FRONT BOTTOM BLACK METAL



Customer #: 1000
BASDENS AMERICAN RV,



CAUSE: glue on j wrap

CORRECTION: took mineral spirits and cleaned off of j wrap.

Labor		Mechanic	Total
Code	Description		
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00
Subtotal for Job #1:			32.00

Job #2 - Warranty

COMPLAINT: DOOR SIDE FRONT COMPARTMENT DOOR WONT LATCH WHEN HINGED UP

CAUSE: latch

CORRECTION: moved latch up just abit to shut.

Labor		Mechanic	Total
Code	Description		
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	16.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Subtotal for Job #2:			16.00

Job #3 - Warranty

COMPLAINT: REAR ENTRY DOOR WONT LATCH WHEN SHUT FROM INSIDE

CAUSE: rear entry door

CORRECTION: adjusted catch .

Labor		Mechanic	Total
Code	Description		
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	16.00
Subtotal for Job #3:			16.00

Job #4 - Warranty

COMPLAINT: SIDE TABLE AND GRIDDLE BRACKETS IS MISSING

CAUSE: parts missing

CORRECTION: need parts to be able to hold grill up

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JG	16.00
Parts				
Part #	Description	Qty	Price	Total
F100387636	TABLE, O/S WALL MOUNT 11 X 23 W/J ED	1.00	27.46	27.46
F100333716	BRACKET, O/S GRIDDLE HOLDER W/BEND L	1.00	7.88	7.88
F100333715	BRACKET, O/S GRIDDLE HOLDER W/ BEND	1.00	7.88	7.88
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-BRACKETS AND TABLE	1.00	32.21	32.21
Subtotal for Job #4:				91.43

W/O: 72788



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 72788

Parts Total:	43.22
Labour Total:	80.00
Sublet Total:	0.00
Extras Total:	32.21
WORK ORDER TOTAL:	155.43

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 16 Feb 2024

Customer Signature : _____



Customer #: 1000
BASDEN'S AMERICAN RV,

