

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 72799  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11320 - 2024 CATALINA 293QBCKLE 5ZT2CAUB4RX030834

VIN: 5ZT2CAUB4RX030834 HIN:

SER#: 5ZT2CAUB4RX030834

Mileage: 0

Work Order Comp: 19 FEB 24

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 02 FEB 24

Inv #: 400940

\*\*\*\*\*

WO #      Job #      Description      JOB INFORMATION

\*\*\*\*\*

72799      2      OUTSIDE SPRAY PORT LEAKS  
REAR OUTSIDE SPRAY PORT LEAKS  
Water dripping from bottom of unit below water connections on  
curbside rear of trailer. Removed rear inside lower bunk  
mattress and board for access to back of water fittings. Found  
spray port leaking where fitting is attached to fitting. This is  
a cemented fitting. Removed outside spray port and found water  
dripping from it where housing and fitting are cemented together.  
Cleaned old putty tape from mounting area and applied new putty  
taps around opening. Connected spray port to water line and leak  
checked. Not leaking. Remounted new spray port and trimmed off  
putty tape around port housing.

72799      1      WATER HEATER LEAKS AT TOP FITTING  
WATER HEATER LEAKS AT TOP FITTING  
Drained water heater down so that top fitting could be removed.  
Removed top water line and fitting from water heater. Cleaned  
all Factory sealer from threads on fitting and pipe nipple to  
water heater. Applied Teflon tape to both threaded fittings.  
Remounted on back of water heater. Filled water heater again and  
pressured. Checked for leaks at both threaded fittings. No  
leaks at this time.

72799      3      THE BEDROOM DOOR WILL NOT LATCH CLOSED. THIS WAS NOTED ON  
DELIVERY  
BEDROOM DOOR WILL NOT LATCH CLOSED. NOTED AT DELIVERY

Claim : 72799

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*  
                  Cleared out material behind latch plate. Remounted latch plate  
                  to allow door to latch closed.

\*\*\*\*\*  
 Part No      Job#      Description      PARTS      Qty      Price      Total  
 \*\*\*\*\*  
 F100073969      2      Shower - Exterior - Spray Port -      0.00      10.11      0.00

\*\*\*\*\*  
 Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*  
 Z990      2      MISC LABOUR CODE (EXTERNAL)      0.35      170.00      59.50  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00  
 Z990      1      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00  
 Z990      3      MISC LABOUR CODE (EXTERNAL)      0.20      170.00      34.00

Parts Total:      0.00  
 Labour Total:      161.50  
 Sublet Total:      0.00  
 Extras Total:      0.00

>>>> Claim Total:      161.50

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_