



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72864
Promised Date:
20 FEB 24

CUSTOMER WORK ORDER

WO #: 72864

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0229 PH TO CLOSE

Stock #: 11324
Stock Desc: 2024 TT COACHMEN
FREEDOM EXPRESS 274RKS
Chassis #: 5ZT2FESB4RW029108
Serial #: 5ZT2FESB4RW029108
Mileage: 0
Licence:

Invoice #:
Date In: 13 FEB 24
Promised: 29 FEB 24
Date Sched:
Completed: 29 FEB 24
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: DRAWER UNDER BED WILL NOT LATCH



Customer #: 1000
BASDEN'S AMERICAN RV,



CAUSE: DRAWER UNDER BED WILL NOT LATCH

CORRECTION: Checked drawer latch Latch mouned off center. straightened latch plunger to align with rollers. checked operation of drawer. Drawer now latches closed.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	16.00
Subtotal for Job #1:			16.00

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR HITS FRAME

CAUSE: BATHROOM DOOR HITS FRAME.

CORRECTION: Loosened door know andadjusted latch. Door is not rubbing now.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00
Subtotal for Job #2:			32.00

Job #3 - Warranty

COMPLAINT: UNIT MISSING 30A POWER CORD

CAUSE: UNIT MISSING POWER CORD AT CHECK-IN.

CORRECTION: Replaced missing power cord.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts Part #	Description	Qty	Price	Total
19-1811	A10-3025ED 30A 25' TWISTLOCK	1.00	74.72	74.72
Subtotal for Job #3:				74.72

Parts Total:	74.72
Labour Total:	48.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	122.72

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Feb 2024

W/O: 72864
Promised Date: 29 FEB 24



Customer #: 1000
BASDENS AMERICAN RV,

