

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1843861
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKC25PX161419
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT274WK
SHERRI A BEASLEY		DEALER RO #	72893
1102 W TENNESSEE ST		CLAIM START DATE	03/09/2024
Evansville, IN 47710		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	03/09/2024	WARRANTY EXPIRATION DATE	03/09/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-106-01-12-001216	Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-09 14:44:52 :: RIGHT REAR SIDE MARKER LIGHT DOES NOT WORK marker light took off side marker light and tested and it didnt work,unplugged wires and got new light from parts and hooked up wires and secured to side ,put on lens and sealed,all good.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-09 14:50:27 :: CHEROKEE DECALS ON BOTH SIDE ARE COMING OFF. decals took pictures of decals and filled out sheet to order new ones.took off decals on both sides with heat gun and installed both decals.			
Model#	Dlr Sub Hrs	0.60	Sub Labor Amt \$102.00	
Serial#	Appr Hrs	0.60	Appr Labor Amt \$102.00	
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	30-99-24-00-001011	Curtains - Interior/Soft Goods/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-09 14:51:06 :: CURTAIN HOLD BACK IS BROKEN curtain hold back took off broken hold back and installed new curtain hold back.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$17.00	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$17.00	
	Notes			

Labor

Line# 4	Operation Code	Operational Description
	40-106-01-11-001249	In-Line Fuse Holder - Electrical/12 Volt Exterior/Replace/Electrical
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2024-03-09 14:51:55 :: THE REFRIGERATOR AND FREEZER	

DOES NOT COOL. frig not getting cold took off bottom cover and found fuse was in crooked,pushed in all the way and it works,put cover back on.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
Notes				

Submitted	Labor Amt	\$187.00
	Parts & Freight	\$0.00
	Total	\$187.00

Approved	Labor Amt	\$187.00
	Parts & Freight	\$0.00
	Total	\$187.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.