



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 72943  
Promised Date:  
03 MAR 24

## CUSTOMER WORK ORDER

WO #: 72943

Customer: 39024 - PROBUS, JULIE A. -  
270-929-9938

Tag:

Author: BH

Location: 0309 CHECK PREAUTH

Stock #: 11276

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 231MKS

Chassis #: 5ZT2CAMB7RU042400

Serial #: 5ZT2CAMB7RU042400

Mileage:

Licence:

Invoice #:

Date In: 26 FEB 24

Promised: 02 MAR 24

Date Sched:

Completed: 09 MAR 24

Warr. Date: 28 FEB 24

### Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Installed new battery. Cut off battery cables to fit and secured all wires. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Recorded all tire serial numbers. Checked awning and roof. Checked power cord. Checked all interior lights. Checked converter output. Added water to fresh water tank and flushed antifreeze from water pump. Connected to city water and checked water system for leaks. Performed Lp drop test and set LP pressure at 10 in.wc. Checked water heater on Lp and electric. Checked all appliances. Checked Air Conditioner. Checked TV and Antenna. Replaced blown fuse in Radio. Moved unit to washbay area.

### Labor

| Code   | Description              | Mechanic | Total |
|--------|--------------------------|----------|-------|
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |
| PDINTT | PDI - NEW TRAVEL TRAILER | DKM      | N/C   |

### Parts

| Part # | Description                         | Qty  | Price | Total |
|--------|-------------------------------------|------|-------|-------|
| DC-24  | ADVANCE GROUP 24 DEEP CYCLE BATTERY | 1.00 | N/C   | N/C   |

Subtotal for Job #FPDINTT: 0.00

### Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: WINTER. WINTERIZE UNIT AND DRAIN HOLDING TANKS \*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE \*\*\*

CORRECTION: By-passed water heater. Blewout all water lines and faucets. Added antifreeze to all water lines and faucets. Poured antifreeze in all drain traps. Drained all holding tanks, including water heater.

### Labor



Customer #: 39024  
PROBUS, JULIE A.



|              |                               |                 |              |
|--------------|-------------------------------|-----------------|--------------|
| Code<br>Z990 | Description<br>WINTERIZE UNIT | Mechanic<br>DKM | Total<br>N/C |
|--------------|-------------------------------|-----------------|--------------|

| Parts  |                           |      |       |       |
|--------|---------------------------|------|-------|-------|
| Part # | Description               | Qty  | Price | Total |
| 24181  | -50 RV ANTI-FREEZE GALLON | 2.00 | N/C   | N/C   |

| Other Services |               |      |       |       |
|----------------|---------------|------|-------|-------|
| Code           | Description   | Qty  | Price | Total |
| SS             | SHOP SUPPLIES | 1.00 | N/C   | N/C   |

**Subtotal for Job #WINTER:** 0.00

**Job #E2 - Internal**

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 10K E2 EQUALIZER HITCH

CORRECTION: Installed hitch brackets on frame of unit.  
 SETUP HITCH HIGHT AND HOOKED UP TO TRAILER. ADJUSTED AS NEEDED.

| Labor |                             |          |       |
|-------|-----------------------------|----------|-------|
| Code  | Description                 | Mechanic | Total |
| Z990  | MISC LABOUR CODE (EXTERNAL) | GAH      | N/C   |
| Z990  | MISC LABOUR CODE (EXTERNAL) | DKM      | N/C   |

| Parts   |                               |      |       |       |
|---------|-------------------------------|------|-------|-------|
| Part #  | Description                   | Qty  | Price | Total |
| 14-1641 | 1000# E2 TRUNION HITCH W/BALL | 1.00 | N/C   | N/C   |

**Subtotal for Job #E2:** 0.00

**Job #BCWT - Internal**

COMPLAINT: BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

CORRECTION: INSTALLED BRAKE CONTROL AND WIRING. USED A OEM TYPE HARNESS AND TESTED 7-WAY OUTPUT. EVERYTHING IS WORKING AS IT SHOULD.

| Labor |                                 |          |       |
|-------|---------------------------------|----------|-------|
| Code  | Description                     | Mechanic | Total |
| BCWT  | BRAKE CONTROL & WIRING - PICKUP | GAH      | N/C   |
| BCWT  | BRAKE CONTROL & WIRING - PICKUP | GAH      | N/C   |

| Parts   |                             |      |       |       |
|---------|-----------------------------|------|-------|-------|
| Part #  | Description                 | Qty  | Price | Total |
| 14636   | 7WAY PLASTIC CAR END        | 1.00 | N/C   | N/C   |
| 19-0938 | 9 WAY CONNECTOR - BRACKET   | 1.00 | N/C   | N/C   |
| 19-1441 | 16-3030 30A CIRCUIT BREAKER | 1.00 | N/C   | N/C   |
| 81799   | 81799 16-22 TOYOTA HARNESS  | 1.00 | N/C   | N/C   |
| 17-0081 | #51120 BRAKE CONTROL        | 1.00 | N/C   | N/C   |

| Other Services |               |      |       |       |
|----------------|---------------|------|-------|-------|
| Code           | Description   | Qty  | Price | Total |
| SS             | SHOP SUPPLIES | 1.00 | N/C   | N/C   |

**Subtotal for Job #BCWT:** 0.00

**Job #HANDLE - Internal**

COMPLAINT: INSTALL LEND-A-HAND

\*\*CHOOSE BLACK OR WHITE\*\*

CAUSE: HANDLE INSTALL LEND-A-HAND

CORRECTION: Marked location of handle. Drilled pilot holes. Applied putty tape to location. Attached handle to trailer with screws provided with handle. Trimmed off excess putty tape around handle mounting area.





| Labor Code | Description                 | Mechanic | Total |
|------------|-----------------------------|----------|-------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | DKM      | N/C   |

| Parts Part # | Description                         | Qty  | Price | Total |
|--------------|-------------------------------------|------|-------|-------|
| 2603892      | GRAB HANDLE W/GRIP - BLACK - LEND A | 1.00 | N/C   | N/C   |

| Other Services Code | Description         | Qty  | Price | Total |
|---------------------|---------------------|------|-------|-------|
| SS                  | SHOP SUPPLIES       | 0.00 | N/C   | N/C   |
| PARTS               | UNINVENTORIED PARTS | 0.00 | N/C   | N/C   |

**Subtotal for Job #HANDLE:** 0.00

**Job #JACK - Internal**

COMPLAINT: INSTALL ELECTRIC TONGUE JACK

CAUSE: JACK INSTALL ELECTRIC TONGUE JACK

CORRECTION: Removed original manual tongue jack. Installed new electric tongue jack. Connected to battery with an inline fuse. Checked operation of new jack. OK.

| Labor Code | Description                 | Mechanic | Total |
|------------|-----------------------------|----------|-------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | DKM      | N/C   |

| Parts Part # | Description                     | Qty  | Price | Total |
|--------------|---------------------------------|------|-------|-------|
| 3291         | 3500# STROMBERG ELEC JACK -BULK | 1.00 | N/C   | N/C   |

**Subtotal for Job #JACK:** 0.00

**Job #1 - Internal**

CUSTOMER TO DROP OFF TRUCK OFF FRI 3-1

**Subtotal for Job #1:** 0.00

**Job #2 - Internal**

COMPLAINT: CHECK THE TOILET AND SEEE IF IT CAN INSTALLED AT A 45DEG

CAUSE: CHECK TOILET TO SEE IF IT CAN BE TURNED AT 45 DEGS.

CORRECTION: Removed water line from toilet. Removed toilet from floor mounting ring. Removed screws from floor mountinr ring. Tried to twist floor mounting ring to 45 degs. Could only twist it approx. 15 degs. Did not want to break floor mounting ring. Reattached floor ring to floor. Remounted toilet to floor. Reconnected water line to toilet. Checked connection for leak.

| Labor Code | Description                 | Mechanic | Total |
|------------|-----------------------------|----------|-------|
| Z990       | MISC LABOUR CODE (EXTERNAL) | DKM      | N/C   |

**Subtotal for Job #2:** 0.00

**Job #3 - Warranty**

COMPLAINT: BLACK TANK LINE PINCH FLAT UNDER SINK

CAUSE: BLACK TANK FLUSH LINE PINCHED FLAT UNDER BATH SINK

CORRECTION: Took picture of pinched black tank flush line under bath sink. Cut flush line on both sides of pinched area. Inserted a brass union and clamped hose on both sides of union. Reconnected hose to flush check valve. Connected water hose to outside tank fitting. Checked for leaks inside under bath sink. No leaks found.





| Labor                |                                   |      |          |       |
|----------------------|-----------------------------------|------|----------|-------|
| Code                 | Description                       |      | Mechanic | Total |
| Z990                 | MISC LABOUR CODE (EXTERNAL)       |      | DKM      | 85.00 |
| Parts                |                                   |      |          |       |
| Part #               | Description                       | Qty  | Price    | Total |
| 8474                 | 1/2" X 1/2" BARBED NIPPLE - BRASS | 1.00 | 6.30     | 6.30  |
| Subtotal for Job #3: |                                   |      |          | 91.30 |

**Job #4 - Internal**

COMPLAINT: WE ARE TO INSTALL A TALLER ELONGATED PORCELIN TOILET AND CHARGE TO SALES PER CHAD

CORRECTION: CHANGED TOILET PER CHAD

| Labor                |                                                         |      |          |       |
|----------------------|---------------------------------------------------------|------|----------|-------|
| Code                 | Description                                             |      | Mechanic | Total |
| Z990                 | MISC LABOUR CODE (EXTERNAL)                             |      | GAH      | N/C   |
| Parts                |                                                         |      |          |       |
| Part #               | Description                                             | Qty  | Price    | Total |
| 7744                 | LIPPERT FLOW MAX RV TOILET<br>ELONGATED PORCELAIN WHITE | 1.00 | N/C      | N/C   |
| Subtotal for Job #4: |                                                         |      |          | 0.00  |

|                          |              |
|--------------------------|--------------|
| Parts Total:             | 6.30         |
| Labour Total:            | 85.00        |
| Sublet Total:            | 0.00         |
| Extras Total:            | 0.00         |
| <b>WORK ORDER TOTAL:</b> | <b>91.30</b> |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 09 Mar 2024

