



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 72960
Promised Date:
20 FEB 24

CUSTOMER WORK ORDER

WO #: 72960

Customer: 54233 - PAKEBUSCH,
BRITTNEY N. - 830-857-0858

Tag:

Author: BH

Location: 0313 CHECK STATUS WITH
BRM

Stock #: 11177

Stock Desc: 2024 5W ALLIANCE RV
PARADIGM 382RK

Chassis #: 7M5FP4225RB203619

Serial #: 7M5FP4225RB203619

Mileage: 0

Licence:

Invoice #: 401823

Date In: 28 FEB 24

Promised: 29 FEB 24

Date Sched:

Completed: 13 MAR 24

Warr. Date: 30 NOV 23

Job #1 - Internal

COMPLAINT: WATER IS LEAKING IN THE WASHER AREA AND DAMAGING THE WOOD

CAUSE: .

CORRECTION: Did not have any water in washer are while testing. I did install a new water valve for cold side. And put the pedestal back in foe washer dryer and sealed and installed new trim. . And reinstalled the washer and dryer.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
11775	VALVE - BLUE - WASHING MACHINE	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: WATER IS LEAKING IN THE SHOWER AREA AND DAMAGING THE WOOD

CAUSE: THE SHOWER DOOR TRACK IS GETTING WATER UNDER THE LOWER TRACK AND RUNNING TO THE FRONT EDGE TOWARD THE WASH MACHINE AND SEEPING AROUND WHERE THE SEALER WAS OPEN AND LETTING IT RUN TO THE PANELING AND SEEP DOWN TO THE FLOOR.

CORRECTION: I HAVE REMOVED THE FRONT VERTICAL RACK AND LIFTED THE LOWER TRACK AND SEALED ALL THE WAY TO THE WALL I CLEANED OFF THE OLD SEALER ON THE WALL AND THEIN REINSTALLED VERTICAL TRACK AND RESEALED LETTING IT DRYNOW 3/4/24 SO I CAN RETEST WITH WATER TO MAKE SURE IT IS FIXED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	340.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00

Parts

Part #	Description	Qty	Price	Total
20156	DOOR JAMB	1.00	14.99	14.99
23278	TRIM - SISC .3125X.6875X108 JAUNT	3.00	15.99	47.97



Customer #: 54233
PAKEBUSCH, BRITTNEY N.

23281 TRIM - BATTEN -BEVELED X 2 3.00 7.99 23.97

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - CRATE	1.00	240.97	240.97

Subtotal for Job #2: 667.90

Job #ALLSEAL - External

COMPLAINT: COMPLETE SEAL INSPECTION. ROOF AND SIDEWALLS. INCLUDES 1 TUBE EACH OF ROOF SEALANT AND SIDEWALL SEALANT.

CAUSE: .

CORRECTION: Checked sides and checked roof. Had to seal. All 4 corners. Roof looks good did not see anywhere it needed sealed .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #ALLSEAL: 0.00

Parts Total: 86.93

Labour Total: 340.00

Sublet Total: 0.00

Extras Total: 240.97

WORK ORDER TOTAL: 667.90

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Mar 2024

W/O: 72960
Promised Date: 29 FEB 24

Customer #: 54233
PAKEBUSCH, BRITTNEY N.