



Warranty Authorization Form

Date: 3/9/2024

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 58851 Unit: 7M5FV392XNA006211
Series: Valor Model: 2022VAL36V11
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 23V701 23V701 - Solar Port Recall - .50hrs - REPLACE
CONNECTORS BETWEEN SOLAR PORT AND SOLAR CHARGE LINES.
INSPECT WITH NO ACTION NEEDED, .50hrs

Fault Code: RECALL-ACTION

Serial #:

Model #:

Notes:

Problem: REPLACE CONNECTORS BETWEEN SOLAR PORT AND SOLAR CHARGE LINES

Time Requested: .5

Cause: diconected battery from unit, got on roof,removed lap seal, removed mounting screws,
and found the wires were corroded and not in the wire nuts, cut new wire ends on unit and solor
conector and put a butt end conector on and electrical taped them and screwed solor conector
back to unit and put self-leveling lap sealent over screw holes and where solor conector meets the
roof

Time Allowed: .5

Sublet Repairs: 0.00

Remedy: diconected battery from unit, got on roof,removed lap seal, removed mounting screws,
and found the wires were corroded and not in the wire nuts, cut new wire ends on unit and solor
conector and put a butt end conector on and electrical taped them and screwed solor conector
back to unit and put self-leveling lap sealent over screw holes and where solor conector meets the
roof

Part Return Req: No

Status: Approved