

e-Authorization

3/20/20
09:11:39

Pre-Authorization number PA03630254 Reference no: 73067
 Working Name Address

Status: Approved
VIN

Approved by stept
Retail sold on

Approved date 3/15/2024

34 Basden's American RV Basden's American RV
 600 E Baseline Rd
 Evansville, IN 47725
 4YDFCGL2XPV502676 2/17/2023

Job Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3401216A Backsplash - Kitcl	0.00	0.20	0.10		1	0.10	Complaint: CUSTOMER ADVISES THAT THE BACKSPLASH BEHIND THE KITCHEN SINK IS COMING LOOSE. Cause: FOUND BACK SPLASH LOOSE Correction: Secured backslash with Brad nails and adhesive
2	3300214A Blind - Venetian -	0.00	1.20	1.00		1	0.20	Complaint: THE WINDOW BLINDS OVER THE CABINET TOP BY THE STOVE HAS A SCREW HANGING DOWN. CUSTOMER ADVISED THAT SCREWS ARE STRIPPED. Cause: NO SUPPORT Correction: Blind stripped out of panel because there isn't any support behind it. Removed trim. Removed panel. Added wood support. Installed panel and trim. Installed blind. Cleaned up mess
3	2103012A Wheel Well - Rep.	0.00	0.20			1	0.50	KRV- approved to repair Complaint: THERE IS SOME INSULATION/CLEAR PLASTIC THAT IS HANGING DOWN NEAR THE LEFT REAR TIRE. Cause: FOUND BUBBLE WRAP Correction: Bubble wrap was stuck around gas line. Removed from line.

KRV - The issue submitted is not considered a warranty defect

Pre-Authorization number PA03630254

1.10

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the