



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73067
Promised Date:
20 MAR 24

CUSTOMER WORK ORDER

WO #: 73067 (Appointment Date: 12 MAR 2024 - Time: 11:00am)

Customer: 53294 - PLUNK, DANNIE J. -
270-977-0721

Tag:

Author: BJW

Location: 0319 BH TO CLOSE

Stock #:

Stock Desc: (11254) 2023 KEYSTONE
COUGAR HALF-TON 24RDS

Chassis #:

Serial #: 4YDFCGL2XPV502676

Mileage:

Licence:

Invoice #: 402011

Date In: 12 MAR 24

Promised: 30 MAR 24

Date Sched:

Completed: 19 MAR 24

Warr. Date:

Job #1 - External

COMPLAINT: CUSTOMER ADVISES THAT THE KITCHEN SINK DOES NOT DRAIN. CUSTOMER NOT SURE IF THERE IS A CAP ON THE TOP OF DRAIN VENT ON THE ROOF OR NOT.

CAUSE: Hooked up to city water. Ran water and sink backed up. I noticed grey tank number 2 is full. Pulled unit into bay and drained grey tank. Water in sink now drains.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE BACKSPLASH BEHIND THE KITCHEN SINK IS COMING LOOSE.

CAUSE: Secured backslash with Brad nails and adhesive

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	17.00

Subtotal for Job #2: 17.00

Job #3 - Warranty

COMPLAINT: THE WINDOW BLINDS OVER THE CABINET TOP BY THE STOVE HAS A SCREW HANGING DOWN. CUSTOMER ADVISED THAT SCREWS ARE STRIPPED.

CAUSE: Blind stripped out of panel because there isn't any support behind it. Removed trim. Removed panel. Added wood support. Installed panel and trim. Installed blind. Cleaned up mess

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	66.30
Z990	MISCELLANEOUS REPAIR	ZMS	103.70

Customer #: 53294
PLUNK, DANNIE J.



Subtotal for Job #3: 170.00

Job #4 - External

COMPLAINT: CUSTOMER ADVISES THAT THE RUNNING LIGHTS ARE NOT WORKING ON THE 4 WAY PLUG AT THE BACK OF THE TRAILER.

CAUSE: Removed underbelly around 4 way. Took a test light to each terminal. Running lights were hooked up to tail light. Secured wires in correct position. tested lights. Secured underbelly.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #4: 0.00

Job #LP - External

COMPLAINT: FILL LP

CAUSE: Filled l.p 3 gallons

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	3.00	N/C	N/C
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #LP: 0.00

Job #6 - Internal

COMPLAINT: THERE IS SOME INSULATION/CLEAR PLASTIC THAT IS HANGING DOWN NEAR THE LEFT REAR TIRE.

CAUSE: Bubble wrap was stuck around gas line. Removed from line.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #6: 0.00

Parts Total: 0.00
 Labour Total: 187.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 187.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 73067
Promised Date: 30 MAR 24

Customer #: 53294
PLUNK, DANNIE J.



Customer Signature : _____

Date: 20 Mar 2024

W/O: 73067
Promised Date: 30 MAR 24



Customer #: 53294
PLUNK, DANNIE J.



Customer Work
Order

