

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1850683
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXPB7RS047185
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT251RBK
		DEALER RO #	73073
		CLAIM START DATE	03/15/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-141-12-00-001592	Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-15 11:39:16 :: BATHROOM SHOWER DOOR WONT CLOSE Shower door won't close. Found shower door wouldn't close, the upper center stop was out of place. Realign center stop and reattach with screws that had fallen behind shower door. Door operates as it should.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-15 11:40:47 :: LEFT SIDE DINNETTE DOOR IS BROKEN OFF open door and found the door fell off need to replace the style that holds the door Additional Note : bhoffman@americanrvcenter.com, 2024-03-15 11:41:59 :: the cabinet door attaches to this wood			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
	Notes			
	This appears to be damage as if the door was caught and ripped off . Can you advise what happened?			
	That is what I would like to know the unit showed up like this			

Labor

Line# 3	Operation Code	Operational Description		
	40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/ Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-15 11:42:17 :: OUTDOOR KITCHEN GFCI IS HANGING OUT OF THE WALL GFCI outlet in outdoor kitchen hanging out Reposition outlet and reinstall outlet.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$51.00
	Notes			

Labor

Line# 4	Operation Code	Operational Description		
	40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/		

Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-03-15 11:43:01 :: THE BEDROOM GFCI IS HANGING OUT OF THE WALL GFCI outlet in bedroom hanging out. Reposition outlet and reinstall

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$51.00

Notes

Labor

Line# 5

Operation Code

30-100-01-00-001044

Operational Description

Drawer Guides or Tracks, pair - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-03-15 11:43:39 :: LEFT HAND SLIDE FOR OUTDOOR GRILL IS BROKEN. found grill slide broken

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00

Notes

Submitted	Labor Amt	\$204.00
	Parts & Freight	\$0.00
	Total	\$204.00

Approved	Labor Amt	\$187.00
	Parts & Freight	\$0.00
	Total	\$187.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.