



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73076
Promised Date:
18 MAR 24

CUSTOMER WORK ORDER

WO #: 73076
Customer: 53019 - DAVIS, BRUCE -
812-549-7250
Tag:
Author: BH
Location: 0325 CHECK PREUATH

Stock #: 11240
Stock Desc: 2023 TT KEYSTONE
SPRINGDALE 311RE
Chassis #: 4YDTSGR20P3100447
Serial #: 4YDTSGR20P3100447
Mileage:
Licence:

Invoice #:
Date In: 13 MAR 24
Promised: 18 MAR 24
Date Sched:
Completed: 20 MAR 24
Warr. Date: 18 MAR 24



Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Replaced battery box lock that came with unit with a normal padlock. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Recorded all tire serial numbers. Checked roof and sealed a couple of voids. Checked awning. Checked electric stab jacks. Checked all interior lights. Checked exterior door lock and all compartment door locks. Cleared out material in door jamb so that dead bolt would lock. Lubed all key locks. Cleaned threads in water heater drain hole. Rebuilt divider panel that covers water pump. Added water to fresh water tank and flushed antifreeze from water pump. Connected to city water and flushed water lines and faucets. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set LP pressure at 10 in.wc. Checked all appliances: Refrigerator, Range, Microwave, Water Heater on LP and Electric, Fireplace and TV. Moved unit to washbay area.

Customer #: 53019
DAVIS, BRUCE

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
52298	PADLOCK LAM 1-1/2" 3DLF - MASTER LOC	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTER WINTERIZE UNIT AND DRAIN ALL HOLDING TANKS *** INCLUDES 2 GALLONS OF ANTI-FREEZE ***





CORRECTION: By-passed water heater. Blew out water lines and faucets, including outside shower. Added antifreeze to all water lines and faucets, including outside shower. Poured antifreeze in all drain traps. Drained all holding tanks, including water heater. To Dewinterize just add water to fresh water tank and flush water pump.

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DKM	N/C
Z990	WINTERIZE UNIT	DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: SWAP CUSTOMERS HITCHWORK

CORRECTION: Unhitch trade-in from customers truck. Removed hitch brackets from trade-in. Installed hitch brackets on customers new trailer. Connected customers truck to trailer and adjusted chains. Checked ride ht. on trailer. Adjusted one link higher. Tightened all bolts securely.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Internal

COMPLAINT: SWAP MATTRESS FROM TRADE

CAUSE: Customer wanted old mattress in new unit

CORRECTION: Moved old mattress to new unit and put new mattress in trade

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE REAR CLEARANCE LIGHT IS OUT

CAUSE: REAR CLEARANCE LIGHT IS OUT

CORRECTION: Removed top rear clearance light. Cleaned off old silicone around light. Connected new light to trailer wiring. Checked operation. OK. Mounted new clearance light. Sealed around light with clear silicone. Checked operation again. OK.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00

Parts				
Part #	Description	Qty	Price	Total
210628	MCL0032RBS 1-LED RED MARKER LIGHT	1.00	4.31	4.31



Subtotal for Job #2: 38.31

Job #3 - Warranty

COMPLAINT: OUTSIDE SHOWER DOOR LOCK FELL APART

CAUSE: OUTSIDE SHOWER DOOR LOCK FELL APART

CORRECTION: Removed key lock from outside shower door that did not work. tumblers fell out of lock when removed from door. Installed new key lock in outside shgower door.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00

Parts

Part #	Description	Qty	Price	Total
L425	L425 5/8" KEYED ECONO CAM LOCK	1.00	5.06	5.06

Subtotal for Job #3: 39.06

Job #4 - Internal

COMPLAINT: CAMPER MISSING LP QUICK CONNECT - NEVER INSTALLED FROM THE FACTORY

CAUSE: CAMPER MISSING LP QUICK CONNECT ON LP LINE, NEVER INSTALLED AT FACTORY

CORRECTION: Removed LP line cap. Installed LP quick connect on LP line. Checked for leak at new fitting. OK

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
06-0954	ME-GMCL-4P QUICK CONNECT FOR NPT FIT	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total: 9.37
 Labour Total: 68.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 77.37

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Mar 2024

W/O: 73076
Promised Date: 18 MAR 24

Customer #: 53019
DAVIS, BRUCE

