

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 1863029
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4MF3F27KH030928
 CHASSIS VIN 1F65F5DY5J0A21268
 MILEAGE 33479
 SITE/WAREHOUSE 068 / 068
 ITEM # F3A30DSF
 DEALER RO # 73087
 CLAIM START DATE 03/27/2024
 CLAIM END DATE 01/01/1900

Labor rate: \$170.00

OWNER INFORMATION

CARL TIM JEWELL
 14151 RANGERS LANDING RD
 Beech Grove, KY 42322
 USA

Retail Date of Purchase 12/18/2018

WARRANTY EXPIRATION DATE 12/18/2019

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 RC-026-05-00-004487 24V103, 2024-086 – "L" BRACKETS FOR LP TANK - PERFORM INSPECTION ONLY
 - Recall/LP Gas System/Inspect/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-03-27 10:41:39 :: PERFORM RECALL 24V103 FOR LP BRACKETS Recall Read instructions on what pics they wanted. too pics

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00

Notes

Please follow the instructions on the recall letter and submit the pictures and information through the QR code provided on the letter or at the following address <https://forestriverinc.com/campaign/24v103>. Please respond to feedback once done. Thanks
 I ALREADY DID THAT
 The bracket has failed inspection. Please order parts and perform the repair.
 Please add a line and use code RC-706-09-00-004517 once the repair is completed.

Labor

Line# 2 Operation Code Operational Description
 RC-706-09-00-004517 24V103, 2024-086 – "L" BRACKETS FOR LP TANK - PERFORM REMEDY - MUST BE APPROVED PRIOR TO PERFORMING - Recall/LPG Tank/Perform/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-05-09 10:26:42 :: PERFORM RECALL 24V103 FOR LP BRACKETS Recall Lp recall Read instructions on what pics they wanted. Drove rv in the shop the made sure the lp was off. Turned on the stove to burn off the remaining lp in the line. Read the instructions for this fix. Unscrewed the lp line from the lp tank. Put a jack under the lp tank. Unbolted the the lp tank from the frame. Lowered the tank. Marked where the holes needed to be drilled then drilled out the holes. Used a reciprocating saw to cut off the leg to the old mount. Cleaned the surface then painted it black. Painted the new parts black. Lifted the lp tank back up and bolted in place. Torqued the bolts to spec. Put the lp hose on and tightened.

Model#	Dlr Sub Hrs	4.00	Sub Labor Amt	\$680.00
Serial#	Appr Hrs	4.00	Appr Labor Amt	\$680.00

Notes

Please add pictures once repair is complete. we need the bracket that is cut off returned.

Submitted	Labor Amt	\$714.00	Approved	Labor Amt	\$714.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$714.00		Total	\$714.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.