

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11833B

Date In: 08 MAY 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11366
: Year: 2025
Customer Name: 17657 - OHARE, MICHAEL Manufacturer: GRAND DESIGN
Address: 8275 EAST HALES CORNER Brand: REFLECTION FW
: STILLMAN VALLEY, IL Model: 320MKS
Postal/Zip: 61084 Miles/Hrs: 0
Phone#(res): 920-621-8705 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: MJOHARE2@GMAIL.COM Tag#:
Purchased Date: 20 MAR 25 :
Delivery Date: 08 MAY 25 :
InService Date: :
Serial#: 573FR3629S9929752 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - a few of the windows are difficult to open. CAUSE: friction between window and frame seems tight between the two. need .10 for repair. CORRECTION: Lubed the windows and opened and closed them a few times seems to work fine now.	WARRANTY REPAIR 1 - a few of the windows are difficult to open. friction between window and frame seems tight between the two. need .10 for repair. Lubed the windows and opened and closed them a few times seems to work fine now.	W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 2 - glass in cabinet door to the right of fireplace has a deep scratch CAUSE: Scratch in glass ORDER NEW CABINET DOOR 11 1/2"WIDE X 34"TALL WITH SMOKEY GLASS INSERT WILL NEED .50 FOR REPAIR. CORRECTION:	WARRANTY REPAIR 2 - glass in cabinet door to the right of fireplace has a deep scratch Scratch in glass ORDER NEW CABINET DOOR 11 1/2"WIDE X 34"TALL WITH SMOKEY GLASS INSERT WILL NEED .50 FOR REPAIR.	W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 3 - trim at bottom of bedroom sliderooms is unfinished looking CAUSE: Mfg unfinished NEED .50 FOR REPAIR CORRECTION: scuffed and prepared area then used black paint pen to cover unfinished areas.	WARRANTY REPAIR 3 - trim at bottom of bedroom sliderooms is unfinished looking Mfg unfinished NEED .50 FOR REPAIR scuffed and prepared area then used black paint pen to cover unfinished areas.	W	1020 GRAND
WARR	COMPLAINT: WARRANTY REPAIR 4 - when flushing toilet the water spurted up to back of toilet and leaks down to flooring CAUSE: Faulty toilet the area where water comes out to flush. The water is coming out of top also should be a sealed fit there. WILL NEED .50 FOR REPAIR. CORRECTION: Removed bad toilet installed new toilet	WARRANTY REPAIR 4 - when flushing toilet the water spurted up to back of toilet and leaks down to flooring Faulty toilet the area where water comes out to flush. The water is coming out of top also should be a sealed fit there. WILL NEED .50 FOR REPAIR. Removed bad toilet installed new toilet	W	1020 GRAND

Continued on page 2

Work Order : 11833B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                hooked up water and ran toilet ,pushed
                                foot pedal many times to make sure there
                                is not a surge of water that gets to
                                rear of toilet toilet is working as it
                                should with no leaks
WARR    COMPLAINT:  WARRANTY REPAIR 7 - bottom edge of           W    1020    GRAND
                                counter above fireplace and on each side
                                of bed is very rough and peeling in some
                                spots
                                CAUSE:           Rough cut edges. NEED .50 FOR REPAIR
                                CORRECTION:     Used fine sand paper to smooth out the
                                rough spots.
WARR    COMPLAINT:  WARRANTY REPAIR 9 - The left facia in           W    1020    GRAND
                                bedroom next to bed is pushed inward a
                                bit looks a bit cockeyed
                                CAUSE:           The wires are behind that area. NOTING
                                ONLY.
                                CORRECTION:     I'm noting saying I noticed but you his
                                is the way it has to be just in case
                                customer sees the bottom portion of
                                facia looks off
WARR    COMPLAINT:  WARRANTY REPAIR 8 - to the right of the           W    1020    GRAND
                                stove it's very easy to see the small
                                countertop that butts up to wall and
                                other side the stove is slanted towards
                                stove
                                CAUSE:           nothing repaired. NOTING ONLY
                                CORRECTION:     NOTING
WARR    COMPLAINT:  WARRANTY REPAIR 10 - the fiberglass           W    1020    GRAND
                                above entrance door has a crack
                                CAUSE:           Looks like when the mfg installed roof a
                                screw that was put in through roof wood
                                panel was out a tad to much and caused
                                fiberglass to crack. WILL NEED TO SUBLET
                                OUT, NOT SURE OF HOURS NEEDED.
                                CORRECTION:     Will need to go to sublet company
    
```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 028985420583 THETFORD STYLE II HIGH W W-1020      1    213.92    213.92
    
```

```

*****
Job# Lab Code Description   LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992   MISC LABOUR CODE (WARR HOD W-1020      0.50  140.00    70.00
ARR02 Z992   MISC LABOUR CODE (WARR HOD W-1020      0.50  140.00    70.00
ARR03 Z992   MISC LABOUR CODE (WARR HOD W-1020      0.00  140.00     0.00
ARR03 Z992   MISC LABOUR CODE (WARR HOD W-1020      0.04  140.00     5.60
    
```

Continued on page 3

Work Order : 11833B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.46   140.00   64.40
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR      W-1020    0.00   140.00    0.00
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1020          213.92   490.00    0.00     0.00    0.00   703.92
      Totals          213.92   490.00    0.00     0.00    0.00   703.92
*****
```

&k2S
&k0S