



Warranty Authorization Form

Date: 4/26/2024

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 62366 Unit: 7M5FV4432NA006354
Series: Valor Model: 2022VAL41V15
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 12086 TRIM - EXTERIOR CORNER MOLDING - *Fault Code:* INCORRECT SIZE
REPLACE

Serial #:

Model #:

Notes:

Problem: CUSTOMER ADVISES THAT THE BLACK VYNYL IS SHRINKING IN THE CORNERS
UNDER THE FIFTH WHEEL OVERHANG.

Time Requested: .5

Cause: Vinyl

Time Allowed: .5

Remedy: Replaced vinyl insert on both lower front corner trim.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved