



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73147
Promised Date:
20 MAR 24

CUSTOMER WORK ORDER

WO #: 73147 (Appointment Date: 22 MAR 2024 - Time: 08:00am)

Customer: 54208 - WILSON, CHAD H. -
812-444-9164

Tag: BJ - PARTS ORDERED 4-4-24

Author: BJW

Location: 0424 BH GAVE BACH TO BJ
TO CLOSE

Stock #: 11186

Stock Desc: 2022 5W ALLIANCE RV

VALOR 41V15

Chassis #: 7M5FV4432NA006354

Serial #: 7M5FV4432NA006354

Mileage: 0

Licence:

Invoice #: 403422

Date In: 22 MAR 24

Promised: 30 MAR 24

Date Sched:

Completed: 24 APR 24

Warr. Date: 17 NOV 23

Job #1 - External

COMPLAINT: SLIDE TOPPER OVER KITCHEN RIPPED FROM
HITTING SOMETHING, NEEDS REPAVED. ALSO
CHECK THAT THERE IS NO DAMAGE TO SLIDE
ROOM OPERATION

CAUSE: Topper

CORRECTION: Remove slide topper from kitchen slideroom. Install new slide topper. Adjust room to fit
tight inside and outside. Remove slide topper from bedroom slide. Put new slide topper on.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Parts

Part #	Description	Qty	Price	Total
9063	AWNING RAIL - BLACK	1.00	N/C	N/C
00-0485	V000165062 7.5' BLK SLIDE TOPPER W/H	1.00	N/C	N/C
00-0486	V000168106 8' BLK SLIDE TOPPER - LIPPERT	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	2.00	N/C	N/C
PUTTY	PUTTY TAPE - ROLL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
FRT	FREIGHT - SEE COMMENTS	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: OUTSIDE LADDER WAS DAMAGED AND NEEDS REPAIRED

CAUSE: Ladder

CORRECTION: Remove damaged ladder. Install new ladder. Remove ladder on roof. Install new one and
dicor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C





Parts

Part #	Description	Qty	Price	Total
9073	COLLAPSIBLE LADDER	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C
13-1287	NON SELF LEVELING DICOR	1.00	N/C	N/C
219088	SILICONE II BLACK	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: VENT OVER REAR BATHROOM IS BROKE.

CAUSE: Vent

CORRECTION: Remove damaged vent. Clean off dicor. Install new vent. Put on dicor. Test

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Parts

Part #	Description	Qty	Price	Total
9062	MAXX AIR PLUS VENT	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	2.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: BLIND IN LIVING ROOM WILL NOT GO UP

CAUSE: Blind

CORRECTION: Remove blind and tighten spring to work right. Put blind back.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: CUSTOMER WOULD LIKE TO KNOW IF AUTOMATIC BLINDS CAN BE ADDED TO MAIN CABIN.

CORRECTION: MOST LIKELY NO. WRITER TO GATHER MORE INFO.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #5: 0.00

Job #6 - External

COMPLAINT: CUSTOMER WOULD LIKE FOR US TO VERIFY THAT BOTH BATHROOM VENTS ARE OPENING AND CLOSING PROPERLY.

CAUSE: Fans

CORRECTION: Turned both fans on and checked lights and air flow on the roof.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Subtotal for Job #6:0.00

Job #7 - External

COMPLAINT: CUSTOMER WOULD LIKE TO KNOW HOW MANY AIR CONDITIONERS CAN BE RAN ON THE GENERATOR AT THE SAME TIME.

CORRECTION: THREE CAN BE RAN. HOWEVER. AMP DRAW CAN CHANGE DEPENDING ON TEMPERATURE AND HUMIDITY. IT IS POSSIBLE THAT, UNDER THE RIGHT CIRCUMSTANCES, ALL THREE A/C UNITS COULD REQUIRE MORE THAN 50 AMPS. IF THIS OCCURS, THERE IS A STRONG POSSIBILITY THAT THE CIRCUIT BREAKER WOULD TRIP. OTHER FACTORS THAT CAN EFFECT AMP DRAW IS OTHER 110V ITEMS IN UNIT. FOR INSTANCE, IFF ALL THREE A/C'S ARE RUNNING ALONG WITH THE MICROWAVE, THEN DEMAND WOULD MOST LIKELY BE HIGHER THAN 50 AMPS AND CIRCUIT BREAKER WOULD TRIP.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #7:			0.00

Job #8 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE ALL SLIDE ROOMS CHECKED AND ADJUSTED IF NEEDED.

CAUSE: Rooms

CORRECTION: Checked all sliderooms and lubricated gears. Only had to adjust kitchen slide

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #8:			0.00

Job #9 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE BLACK VYNYL IS SHRINKING IN THE CORNERS UNDER THE FIFTH WHEEL OVERHANG.

CAUSE: Vinyl

CORRECTION: Replaced vinyl insert on both lower front corner trim.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	42.50
Z990	MISC LABOUR CODE (EXTERNAL)	BB	42.50
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Subtotal for Job #9:			85.00

Job #10 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THE RIP IN THE ROOF BY THE LADDER FIXED OR PATCHED.

CAUSE: Roof

CORRECTION: Cut out damaged gutters. Patch roof with extreme tape. Put new gutters on. Silicone. Put dicor on edges. Put plastic insert back.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C



W/O: 73147
Promised Date: 30 MAR 24



Customer #: 54208
WILSON, CHAD H.





Parts				
Part #	Description	Qty	Price	Total
38-9089	QUICK ROOF EXTREME 6" X 25"	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	6.00	N/C	N/C
E569	E569 HEAVY DUTY INSERT TRIM MOLDING	1.00	N/C	N/C
Subtotal for Job #10:				0.00

Job #11 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THE GUTTER TRIM THAT RUNS ACROSS THE WHOLE LENGTH OF THE BACKSIDE OF THE TRAILER.

CAUSE: Check

CORRECTION: There is a gutter above fold down rear door. Has both spots.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #11:			0.00

Job #12 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THE ROOF DOUBLE CHECKED ESPECIALLY AROUND THE DAMAGED AREA.

CAUSE: Roof

CORRECTION: Touched up a few spots

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Subtotal for Job #12:			0.00

Parts Total:	0.00
Labour Total:	85.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	85.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 26 Apr 2024

Customer Signature : _____

