



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73225
Promised Date:
20 APR 24

CUSTOMER WORK ORDER

WO #: 73225 (Appointment Date: 30 MAR 2024 - Time: 10:00am)

Customer: 39024 - PROBUS, JULIE A. -
270-929-9938

Tag:

Author: BH

Location: 0415 BH TO CLOSE

Stock #: 11276

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 231MKS

Chassis #: 5ZT2CAMB7RU042400

Serial #: 5ZT2CAMB7RU042400

Mileage:

Licence:

Invoice #:

Date In: 29 MAR 24

Promised: 30 APR 24

Date Sched:

Completed: 17 APR 24

Warr. Date: 28 FEB 24

Job #1 - External

COMPLAINT: Transferred to BAS*73361 on 12 APR 24

Estimate amount was 0.00

CUSTOMER TRADED A TOYOTA TACOMA FOR AND F150 AND HE NEEDS TO HAVE THE HITCH RESET.

CORRECTION: RESET HITCH HIGHT AND HOOKED UP TO TRAILER. ADJUSTED HITCH AS NEEDED TO WORK WITH TRUCK AND TRAILER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #51-1722 - Warranty

COMPLAINT: ROOF MOUNT SOLAR INLET IS LEAKING

CAUSE: REMOVED DICOR.REMOVED SOLAR INLET. CUT WIRES. SECURED NEW INLET WIRES. SECURED INLET. SEALED WITH DICOR.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	69.70
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	15.30

Parts

Part #	Description	Qty	Price	Total
F100530500	CABLE ENTRY ROOF PLATE FOR SOLAR SYS	1.00	9.49	9.49

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-RECALL PIECE	1.00	17.30	17.30

Subtotal for Job #51-1722: 111.79

Job #2 - Warranty

COMPLAINT: CABINET NEXT TO RIGHT HAND RECLINER IS SMASHED IN



Customer #: 39024
PROBUS, JULIE A.

CAUSE: Cabinet

CORRECTION: Move couch. Remove side panel and trim. Remove 12v to USB and outlet. Remove front panel. Cut new panel and cut out holes. Install new panel. Hook up outlet and 12v. Put side panel back and trim. Put couch back

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	51.00

Subtotal for Job #2: 51.00

Job #3 - Warranty

COMPLAINT: SLIDING DOOR FOR THE BEDROOM HAS A HINGE THAT KEEPS COMING OFF CAUSING THE DOOR TO FALL

CAUSE: Door hanger won't latch on the top of the door. Replaced door hanger and installed door.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	51.00

Parts

Part #	Description	Qty	Price	Total
H529	H529 2-pk SLIDING DOOR HANGER	1.00	6.05	6.05

Subtotal for Job #3: 57.05

Parts Total: 15.54
Labour Total: 187.00
Sublet Total: 0.00
Extras Total: 17.30
WORK ORDER TOTAL: 219.84

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 Apr 2024

W/O: 73225
Promised Date: 30 APR 24



Customer #: 39024
PROBUS, JULIE A.

